


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised June 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form



Release Notification and Corrective Action

OPERATOR

Initial Report ☒ Final Report

Name of Company	Burlington Resources	Contact	Jay Ely
Address	P.O. Box 4289 Farmington NM 87499	Telephone No.	(505) 326-9700
Facility Name	PIERCE SRC 1A	Facility Type	Gas Well

Surface Owner	Federal	Mineral Owner	Federal	Lease No.	NMSF-078134
---------------	---------	---------------	---------	-----------	-------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	30	031N	010W	1020	South	1455	East	San Juan

NATURE OF RELEASE

Type of Release	Condensate	Volume of Release	38 BBLS.	Volume Recovered	0 BBLS.
Source of Release	Oil Storage Tank	Date and Hour of Occurrence	2/16/2004	Date and Hour of Discovery	2/16/2004
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Denny Foust		
By Whom?	Gregg Wurtz	Date and Hour	2/16/2004		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	0		

If a Watercourse was Impacted, Describe Fully.\*

NA

Describe Cause of Problem and Remedial Action Taken.\*

Vandals had cut the cable entering location and then had opened the load valve on the oil storage tank. Condensate was released out into the bermed area only. Not certain if any condensate was stolen or if all was spilled. Soil was excavated within the berm area. Impacted soils were removed to approximately 4 feet in the north half and 10 feet in the south half of the berm area. Soils were excavated to less than 100 ppm VOC using the field headspace technique. Sandstone bedrock was hit at the bottom of the excavation.

Describe Area Affected and Cleanup Action Taken.\*

All fluids were contained inside the bermed area. Impacted soils were excavated and landfarmed onsite.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Gregg Wurtz	Approved by District Supervisor: for Frank Chavez		
Title: Environmental Representative	Approval Date: 3/1/04	Expiration Date:	
E-mail Address: lhasely@br-inc. com or gwurtz@br-inc.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 2/23/04 Phone: (505) 326-9841 or 9537			

\* Attach Additional Sheets If Necessary

1 DGF0406149940