

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR



☐ Initial Report ☒ Final Report

Name of Company BP America Production Company	Contact Don Brooks	
Address 200 Energy Court Farmington, NM 87401	Telephone No. (505) 326-9425	
Facility Name Blanco 2	Facility Type Wellsite	
Surface Owner BLM	Mineral Owner BLM	Lease No. 30-045-27523

LOCATION OF RELEASE

Unit Letter B	Section 5	Township 31N	Range 8W	Feet from the 1095	North/South Line FNL	Feet from the 1740	East/West Line FEL	County San Juan County
-------------------------	---------------------	------------------------	--------------------	------------------------------	--------------------------------	------------------------------	------------------------------	----------------------------------

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 10 bbls	Volume Recovered 10 bbls
Source of Release Produced Water Tank	Date and Hour of Occurrence March 7, 2004 6:00 AM	Date and Hour of Discovery March 7, 2004 6:45 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* This well was on a regularly scheduled haul, and was due to be pulled on Saturday (3/6/04). The driver did not show up to work, and once discovered, a driver was sent out immediately Sunday morning. 10 barrels of produced water was released into the berm, with all 10 barrels recovered. Met with water hauling company to discuss how the missing driver was never accounted for. They identified that they may have too much responsibility for one dispatcher, so added additional resources to reduce workload and increase focus to ensure all drivers are accounted for.		
Describe Area Affected and Cleanup Action Taken.* The spilled material was contained and cleaned up with the vacuum truck immediately.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Donald Brooks	Approved by District Supervisor:  for Frank Chavez	
Title: Environmental Management System Coordinator	Approval Date: 3/29/04	Expiration Date:
Date: 03/10/2004 Phone: (505) 326-9425	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

NDGF0409330268