

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	BP America Production Company	Contact	Brittany Benko
Address	200 Energy Court Farmington, NM 87401	Telephone No.	(505) 326-9235
Facility Name	GCU 412 water pipeline	Facility Type	Produced Water Pipeline
Surface Owner	BLM	Mineral Owner	BLM
		Lease No.	30-045-28759

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	12	28N	12W	1010	FSL	995	FEL	San Juan County

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	15 bbls	Volume Recovered	10 bbls
Source of Release	Produced Water Pipeline	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	February 12, 2004 12:32 PM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required				
By Whom?	If YES, To Whom?				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				
Date and Hour					
If YES, Volume Impacting the Watercourse.					

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A Production Tech, while checking his wells noticed water running across a lease road. The water was coming from a valve can next to the road. He called a water truck and shut in two wells feeding one line and shut in a transfer station down the road. After excavating the spill site, the dresser sleeve was found to be leaking because of corrosion of the bolts. A new dresser sleeve was applied. The patched area of the pipeline will be excavated and replaced when weather permits.

Describe Area Affected and Cleanup Action Taken.*

A water truck was called and recovered produced water from the valve can. The impacted soil was removed and landfarmed on the GCU 412 location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Brittany Benko</i>		OIL CONSERVATION DIVISION	
Printed Name: Brittany D Benko		Approved by District Supervisor: <i>for Frank Chavez</i>	
Title: Environmental Coordinator		Approval Date: 3/1/04	Expiration Date:
Date: 02/20/2004	Phone: (505) 326-9235	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

n DG F0406148691