District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenuc, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action OPERATOR Initial Report Final Report **Burlington Resources, a wholly** Kelsi Gurvitz Name of Company Contact owned subsidiary of ConocoPhillips Company 3401 E. 30th St., Farmington, NM 87402 505-599-3403 Telephone No. API # 300-45-34908 Lively #25M Gas Well Facility Name Facility Type Federal Mineral Owner Federal Lease No. NM-012708 Surface Owner LOCATION OF RELEASE

Feet from the North/South Line Feet from the East/West Line County Unit Letter Section Township Range **T30N R08W** 1262' North 1825' East San Juan В 29 36.78599° N Longitude 107.69630°W Latitude NATURE OF RELEASE Type of Release - Drilling Fluids Volume of Release - 60 BBL Volume Recovered - 0 BBL Source of Release: Date and Hour of Occurrence Date and Hour of Discovery Hole in liner 9/5/09 - 10:00 p.m. 9/5/09 - 10:30 p.m. If YES, To Whom? Was Immediate Notice Given? RCVD APR 26'10 **Brandon Powell- verbal** Date and Hour - 9/6/09 9:00 a.m. **Gregg Wurtz** By Whom? OTL COMS DEU Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes ⊠ No DIST 3 If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* On September 5, 2009, a hole in the pit liner above the water line was caused by the force of the water returning from the centrifugal pump. The pump was shut down and the hole in the liner was covered with a skirt to prevent further fluid loss. All fluid remained on location. Due to manufacturing problems with the liner material, COPC discontinued use of the temporary pit. Describe Area Affected and Cleanup Action Taken.* All fluid remained on location. A vacuum truck was called to location but fluids were unrecoverable. A five (5) point composite sample was taken from underneath the liner & analytical results demonstrated that the release did exceed the concentrations specified in Subparagraph (b) of Paragraph (1) Subsection B of 19.15.17.13 NMAC; therefore no remedial action was taken. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Kelsi Gurunitz OIL CONSERVATION DIVISION Signature:

Signature:

Printed Name: Kelsi Gurvitz

Approved by District Supervisor: Francisco Julius For: CP

* Attach Additional Sheets If Necessary

NBP1027139620