

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(*See instructions on re-
verse side)Form approved
Budget Bureau No. 42-R1421

5. LEASE DESIGNATION AND SERIAL NO.

NM 052931

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER <u>Water Injection</u>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR <u>Tesoro Petroleum Corporation</u>		8. FARM OR LEASE NAME <u>Hanson</u>	
3. ADDRESS OF OPERATOR <u>8520 Crownhill Boulevard, San Antonio, Texas 78209</u>		9. WELL NO. <u>20</u>	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) <u>At surface Unit Letter N</u> <u>5' from the South Line and 2635' from the West Line</u>		10. FIELD AND POOL, OR WILDCAT <u>South Hospah-Upper Sand</u>	
14. PERMIT NO. <u>?</u>		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 6, T17N, R8W, NMPM</u>	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>6910' GL 6922' RKB</u>		12. COUNTY OR PARISH <u>McKinley</u>	
		13. STATE <u>New Mexico</u>	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐CompletionREPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐X

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6-11-70: Ran Dresser-Atlas Strip Log and perforated the following intervals:
1539-41' RKB; 1549-53' RKB; 1557-61' RKB; 1565-68' RKB, with 4 shots
per foot.6-22-70: Acid washed perforations with 300 gals. 15% NE acid at 550 psi. Ran
tubing, Baker-Lok-Set packer at 1508' RKB. Swabbed well down for completion
as injection well.

RECEIVED

AUG 3 1970

U. S. GEOLOGICAL SURVEY
FARMINGTON, N.M.

RECEIVED

AUG 4 1970

OIL CON. COM.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED R. A. KinnearTITLE Petroleum EngineerDATE July 29, 1970

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

*See Instructions on Reverse Side