



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

GARREY CARRUTHERS
GOVERNOR

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

February 20, 1987

Mr. Bob Durben
Tesoro Petroleum Corp.
Star Route 2
Cuba, NM 87013

Dear Bob:

Listed below are 6 of your injection wells which are exceeding pressure limitations.

Hanson #28 reported pressure 324 limit 315
Hospah Sand Unit #87 reported pressure 392 limit 307
Hospah Sand Unit #91 reported pressure 316 limit 300
Hospah Sand Unit #93 reported pressure 356 limit 300 - 1000
SFRR #10 reported pressure 319 limit 315
SFRR #25 reported pressure 322 limit 315

In order to comply with the order authorizing injection, you are directed to cut back injection until you are in compliance.

Yours truly,

Charles Gholson
Deputy Oil & Gas Inspector

CG/dj

cc: Well Files
Operator File
OIC Files
Prentiss Childs