N S P E C T I O N	L A S S I F	A C I	O I	QUARE HOURS	Name Charles G. Time of Departure In the space beloperformed, listing	7:00 AM Tir	ne of Retur	cn <u>6:00</u>	PM Car N	o. <u>6603</u> duties:	3_	
P	R	0			One Well 14N- From Grants to at the Manvar (1274). Set "A" cement. shots/ft. Had no effect sacks of class Woc 3 hours. Casing 410 40 flow estimate Flow was comm with 250 sack water flow go about 100 sac at surface ho 4 1/2" casing Grants.	o North of Sa #1. Finishe a cement plug Perforated 4 d estimated f on surface f s "B" cement Tagged top o d with 2 sho d at 100 - 20 unicating wit s of class "B ing up casing ks had been p lding water f	d going i 1274 — 1/2" casi resh wate low. Squ w/3 % CaC f c'ement ts/ft. G O gal./mi h surface " cement umped. S low. Lef night.	n hole 1054 wi ng 710 er flow eezed p 12. Sh at 564' Got a he n. up of eflow. with 3% broke Shut in t Brade	with tube th 20 sac - 720' we of 30 gal eerfs. with out off wa . Perfor eavy frest casing. Squeezed to surface Bradenhead enhead shu	ing to TD cks cass th 2 ./min. th 150 ter flow. teted wated Water Bradenhe Left ce after d. Cemen tin and	ad	
					Mileac UI C	ge	Per Diem UIC		Hours UIC			
					RF A	80	RFA	48.00	RFA _	11		
					Other	· · · · · · · · · · · · · · · · · · ·	_ Other		Other_		:	
		את אפ		100		INSPECTION CLASSIFICATION				NATURE OF SPECIFIC WELL OR FACILITY DESPECTED		
P	- Plu	sekec ggi ng gging	-	mu z o	related to	U - Underground Injection Control - any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry				D - Drilling P - Production 1 - Injection		

T - Well Test

R - Kepair/Horkover

F - Waterflow

H - Mishap or Spill W - Water Contemination

0 - ಯರ್ಷ

injection and production wells, water flows, or pressure tests, surface injection equipment, plugging, etc.)

- R Inspections relating to Reclamation Fund Activity
- O Other Inspections not related to injection or the reclaration fund
- E Indicates some form of enforcement action in the field .

 (show immediately below the letter U.R.or O)

1 - Injection
C - Corbined production/
injection operations
S - SWD
U - Underground Storage
G - General Operation
F - Facility or location

- H Heeting
- 0 Other