State of New Mexico Energy, Minerals and Natural Resources Department

Revised 1-1-0

DISTRICT | P.O. Box 1980, Hobbs, NM 88240

OII

DISTRICT II P.O. Drawer DD, Artesia, NM 68210

RICT III Rio Benzos Rd., Antec, NM 87410

CONSERVATION DIVISION	
P.O. Box 2088	WELL AM NO 30-031-20865
Santa Fe, New Mexico 87504-2088	30 031-20003

5. Indicate Type of Laure STATE ## L LG 2779

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					7. Lesse Name of Ball Agreement Name					
1. Type of Well Oil. Will.	-	MET []		OTHER			ST	ATE		
Name of Open Enerdyn	e Corpo	ration					1. We	li No.		
P.O. Bo Well Location	x 502 A	Albuque	rque, N	N.M. 8	7103			d mane or Wildo Co Wash		erde
		. 990	Fest From T	he <u>No</u>	rth	Line and 300		Foot From The	East	Line
Section	28	· · · · · · · · · · · · · · · · · · ·	Township	20N	R	mge 9W	NMPM	McKinle	у	County
			10. E	evation (Show 5428 'G	whether R	DF, RKB, RT, GR, etc.)				
11.	NOTICE (Obeck Ap OF INTE	propriate I NTION TO	Box to Ind	licate l	Nature of Notice, R		or Other Da		
PERFORM REME	DIAL WORK		PLUG AND	ABANDON	X	REMEDIAL WORK		☐ ALTI	ering Casin	1G 🗆
TEMPORARILY A	BANDON		CHANGE !	PLANS		COMMENCE DRILLING	OPNS.		FARARA	SOMET F
PULL OR ALTER	CASING					CASING TEST AND CE	MENT J			I V E
OTHER:						OTHER:			AUG11	
12. Describe Prop work) SEE R	osed or Comple ULE 1103.	ted Operation	Clearly state	ali pertinent d	letails, es	i d give persinent dates, inclu	ding action	med dan of will	L.G.∂. ₩	
Work to	be com	pleted	by Dec	ember	31,	1992.				•
Casing: PBTD: Perfs:	Cement	ed wit	h 32 sk	s(38 c	5' GI u. ft	R. E.) class B. (Circu	ılated c	ement.	
Propose	d Plugg	ing Pr	ocedure	: Pull	l suc	ker rods and	tubi	ng out	of hole	<u>.</u>

The proposed cement volume includes 12% excess over the theoretical casing capacity. Install an appropriate dry hole marker. Vice President **ТИЛЕ НО 291-9502** Frank Welker TITE OR PROTINGE

(This space for Blate Use)

Original Signed by CHARLES GHOLSON

DEPUTY OIL & GAS INSPECTOR, DIST. #3

Remove well head. Install a 4" X 2" swedge. Fill the casing with cement, by pumping 27 sks(32 cu.ft.) class B neat cement.

CONDITIONS OF APPROVAL, IF ANY: