

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 42-R1424

LEASE DESIGNATION AND SERIAL NO.
Apache Tribal No. 71

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use APPLICATION FOR PERMIT for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry Hole
2. NAME OF OPERATOR
Chace Oil Company, Inc.
3. ADDRESS OF OPERATOR
313 Washington, S.E., Albuquerque, New Mexico 87108
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface Unit K-Sec. 9, T-23-N, R-4-W, 1850' Southline
and 2390' West Line of Section
14. PERMIT NO.
15. ELEVATIONS (Show whether DE, RT, GR, etc.)
2068 GR

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla Apache
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Jicarilla Reservation
9. WELL NO.
284
10. FIELD AND POOL, OR WILDCAT
Ballard PC
11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Sec. 9, T-23-N, R-4-W
12. COUNTY OR PARISH
Rio Arriba
13. STATE
N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)
PULL OR ALTER CASING
MULTIPLE COMPLETION
ABANDON* X
CHANGE CLASS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)
REPAIRING WELL
ALTERING CASING
ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS, giving pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.*

8-15-72 Set 100' 8-5/8" Surface Casing. Cemented w/100 sxs.
8-18-72 Reached T.D. 2957' (Driller)
8-19-72 Logged (Schlumberger)
Tops: Alamo 2450'
Kirtland 2402'
Pictures Cliffs 2223'

Well Plugged and Abandoned

Placed 100' plug across P.C. formation from 2675-2775' (25 sxs)
Placed 250' plug across Alamo formation from 2200-2450' (65 sxs)
Placed 50' plug bottom of surface csg. from 75' to 125' (12 sxs)
Placed 10 sxs from surface down, placed marker on location showing well and location

Reason for Abandonment - No commercial zone of production was encountered.

18. I hereby certify that the foregoing is true and correct

SIGNED

James M. McLaughlin

President

(This space for Federal or State office use)

DATE August 20, 1972

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

DATE

NOV 30, 1972

JERRY
DISTRICT

*See Instructions on Reverse Side

St

ILLEGIBLE