Form: 3160-5 (November 1993)

TEST WATER SHUT-OFF

PRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

UNITED STATES BUBMIT IN TRIPLICATE* (Other instructions on rerespectively)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

Budget Bureau No. 1004-0135 Expires August 31, 1985

			- /	
5.		DESIGNATION	BBBLAL	NO
	JIC.	361		

REPAIRING WELL

ALTERING CASING

Formerly 9-331) ULPAI BUI	JIC. 361		
SUNDRY N (Do not use this form for p	OTICES AND REPORTS ON WELLS roposals to drill or to deepen or plug back to a different reservoir. PLICATION FOR PERMIT—" for such proposals.)	Jicarilla Apache	HAME
OIL GAS X	mat 1	7. UNIT AGREEMENT NAME	
	8. PARM OR LEASE NAME		
Amerada Hess Corpor	Jicarilla Apache ".	Jicarilla Apache "J"	
	9. WBLL NO.		
ADDRESS OF OPERATOR	Non Mariaa 88265	3 .	
Drawer D, Monument,	10. PIELD AND POOL, OR WILDCAT	,	
LOCATION OF WELL (Report local See also space 17 below.) At surface	S. Blanco P.C.		
875' FNL & 900' FWL	11. SEC., T., E., M., OR BLE. AND SURVEY OR AREA		
		Sec. 4, T23N, R4W	
	15. BLEVATIONS (Show whether DF, RT, QR, etc.)	12. COUNTY OR PARISH 18. STAT	T B
4. PERMIT NO.	7158' GR	Rio Arriba N.M.	
6. Checl	Appropriate Box To Indicate Nature of Notice, Report,	or Other Data	
NOTICE OF	INTENTION TO:	BESQUENT REPORT OF:	

(Nors: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) TA-Test csg. 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.) * (Other)


WATER SHUT-OFF

(Other)

SHOOTING OR ACIDIZING

Amerada Hess Corporation requests to extend the Temporary Abandonment of the Jicarilla Apache "J" #3 for another year. The previous TA period expired on April 3, 1990. To comply with BLM temporary abandonment requirements, the Jicarilla Apache " \acute{J} " #3 casing will be pressure tested to 500 PSI to insure integrity. A BLM field inspector will be notified prior to the test.

Plan to complete test within 60 day period.



	graphs of the control		
SIGNED Signed and correct	TITLE District Superintendent		
(This space for Federal or State office use)			
APPROVED BY	TITLE		
		Carl Transfell	

*See Instructions on Reverse Side