

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

(Other instructions on reverse side)

Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Union Texas Petroleum Corporation

3. ADDRESS OF OPERATOR

P.O. Box 1290, Farmington, New Mexico 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below.)
At surface 1768' FSL; 2235' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether on RKB, etc.)

7242' RKB

5. LEASE DESIGNATION AND SERIAL NO.

SF 078272 A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Dunn

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Lybrook Gallup/Undes. Dakota

11. SEC., T., R., N., OR BLK. AND SURVEY OR AREA

Section 9, T23N-R7W NMPM

12. COUNTY OR PARISH 13. STATE

Rio Arriba New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Proceeded with plug and abandonment, as approved, on 1-14-84.

1. Tripped in hole w/DP to 1589' RKB, and set 1st plug w/77 cu.ft. Cl B cement.
2. Pulled DP to 683' RKB and set 2nd plug w/53 cu.ft. Cl B cement.
3. Pulled DP to 309' RKB and set 3rd plug w/35 cu.ft. Cl B cement.
4. Pulled DP and set surface plug with 23 cu.ft. Cl B cement.
5. Cut off casing head.
6. Install dry hole marker.

RECEIVED
FEB 14 1984
OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

J. A. Edmister

TITLE

Engineering Analyst

DATE

February 7, 1984

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

WMOCC

*See Instructions on Reverse Side