orm 3160-5 November 1983) Budget Bureau No. 1004 0135 UNITED STATES UNITED STATES

BURMIT IN TRIPLICATES

DEPARTMENT OF THE INTERIOR (Other Instructions on re-Expires August 31, 1985 formerly 9-331) D. LEASE DESIGNATION AND BREIAL NO. BUREAU OF LAND MANAGEMENT ∕ic. Contract 430 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT" for such proposals.) Jicarilla. 7. UNIT AGREEMENT NAME WFLL X WELL OTHER ?. NAME OF OPERATOR 8. FARM OR LEASE NATE Merrion Oil & Gas Corporation Jicarilla 430 3. ADDRESS OF OPERATOR 9. WELL NO. P. O. Box 840, Farmington, New Mexico LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface 6 10. FIELD AND POOL, OR WILDCAT RECEIVED Undes. Gallup 990' FNL and 1650' FWL 11. SEC., T., S., M., OR BLK. AND SURVEY OR AREA JUN 2 5 1985 Sec. 36, T23N, R5W 14. PERMIT NO. 15. PLEVATIONS (Show whether Dr. ST. GR, etc.) 12. COUNTY OR PARISH 13. STATE 6810' GL Sandoval New Mexico 18 Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: BUBREQUENT REPORT OF: TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL FRACTURE TREAT MULTIPLE COMPLETE PRACTURE TREATMENT ALTERING CARING BHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING ABANDONMENT* REPAIR WELL CHANGE PLANS (Other) (Norm: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) Repair casing cement 17. DESCRIBE PROPOSED OR COMPLETED DIFFRACIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any next to this work.) * Reguest permission to repair casing cement by perforating @ 3910' KB, establishing circulation to surface out bradenhead. Cement with 650 sx Class B 2% D-79 followed (1339 cu ft by 50 sx Class H to cover Mesaverde-Cliffhouse, Pictured Cliffs, Fruitland and Ojo Alamo. (60 cu. ft.) If unable to establish circulation will perforate above and below Cliffhouse under retainer. Perforate below Fictured Cliffs @ 2250' and above Ojo Alamo, establish circulation behind pipe and place cement from 2250' to 1600' to isolate these formations. (As per verbal approval - Steve Mason, BLM.) Top of cement estimated @ 3860' to 3910' from cement bond log. 18. 1 1. roby certify that the foregoing is true and gorrect Operations Manager (This space for Federal or State office use)

Tiple 18 U.S.C. Section 1991, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as - any matter within its jurisdiction.

*See Instructions on Reverse Side

FARMINGTON PLOCUPUR APPEA

CONSTITUENS OF APPROVAL, IF ANY: