



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

OIL CONSERVATION DIVISION
BOX 2088
SANTA FE, NEW MEXICO 87501

DATE 4-14-86

RE: Proposed MC _____
Proposed DHC _____
Proposed NSL X _____
Proposed SWD _____
Proposed WFX _____
Proposed PMX _____

Gentlemen:

I have examined the application dated 4-11-86
for the Kirby Exploration Co. Boling Federal 22#9 E-22-19N-3W
Operator Lease and Well No. Unit, _____

and my recommendations are as follows:

Docket for hearing, rule 104F does not give
Waco power to grant approval based on
geology

Yours truly,

Tom Lynch



KIRBY EXPLORATION COMPANY OF TEXAS

April 10, 1986

RECEIVED
APR 11 1986
OIL CON. DIV.
DIST. 3

State of New Mexico
Oil Conservation Commission
District III
1000 Rio Brazos Road
Aztec, New Mexico 87410

RE: Sandoval County, New Mexico
Media Entrada Southwest Field
NWY4 Sec. 22, T19N, 3W
Boling Federal No. 9-22

Gentlemen:

Kirby Exploration Company of Texas requests administrative approval for the drilling of the Boling Federal 9-22E well located 1327 FNL & 1313 FWL of Section 22, T19N, R3W, Sandoval County, New Mexico per the attached plat. This is an unorthodox location in that it does not conform to the Media Entrada Southwest Field spacing specifications described in Rule 4, Order R-4822-A and R-4822-C, namely "...Nearer than 330 feet to any governmental quarter-quarter section line ...". We feel the requested permit to drill should be granted without a hearing for the following reasons:

- I. Geological and Engineering evidence support for the proposed location as optimum to drain maximum reserves and prevent waste.
- II. No other wells are producing from the Entrada or any other formation in Section 22 of the Media Entrada Southwest Field.
 - A. Fluid Power Pump #5, which is temporarily abandoned at present, is a Gallop SWD well. The Entrada sand was cement squeezed and capped with a cast iron bridge plug in January of 1979.
 - B. Boling Federal #8-22 is shut-in due to uneconomic production. It last produced in April, 1985, 202 BO & 73850 BW.

April 10, 1986

- C. Federal #6-22 is shut-in due to uneconomic production. It last produced in February, 1986, 200 BO & 80,000 BW.
- D. Miller Federal #7-22 was shut-in July, 1983 after watering out.

III. Kirby Exploration Company of Texas owns 100% working interest and is the only operator in the Media Entrada Southwest Field, Section 22, and Media Entrada Unit located in Sections 14 & 15.

IV. Lease owners of contiguous 160 acre tracts in Sections 15, 21, & 22 are being notified for solicitation of drilling waivers. Currently no producing wells have been drilled on any contiguous acreage in the mentioned sections not owned by Kirby Exploration Company of Texas.

If any additional information is needed, please feel free to call (713) 629-9370. Your immediate attention to our request would be most appreciated.

Yours very truly,



James L. Kovar
Regulatory Supervisor

JLK:RGB:M
Attachment