

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office _	Santa Fe
Lease No	078851
Unit	E <b>ngli</b> sh

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL			
-	II.	OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT	OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		OF ALTERING CASING	1 1
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT	OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WE	L HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	X		
NOTICE OF INTERTION TO ABARDON VIELE			
(INDICATE ABOVE BY CHECK MARK I	ATURE OF REPORT, NOT	ICE. OR OTHER DATA)	
		October 16	, 19 <u>52</u> _
Vell No. 1 is located 1650 ft. fr	GW N. M	P. M. (Meridian)	
Wildcat Sai (Field) (Count:	or Subdivision)	New Mexico (State or Territor	<del>y</del> )
State names of and expected depths to objective s	ILS OF WORK ands; show sizes, wei	ghts, and lengths of prope	osed casings;
indicate muddling jobs, cementing point is intended to abandon this well  1. Plug between Dakota - Mo 2. Plug between Dakota - Mo 3. Plug between Mancos - Mo 4. Plug between Mesaverde 5. Plug across Pictured Cl 6. Plug across water sand. 7. Plug in top of hole wit	by setting ceme orrison Contact. ancos Contact. esaverde Contact. Lewis Contact. Iffs formation.	nt plugs at the fo	
indicate muddling jobs, cementing post.  It is intended to abandon this well.  1. Plug between Dakota - Markota - Ma	by setting ceme orrison Contact. ancos Contact. esaverde Contact. Lewis Contact. lffs formation. h 4" marker pipe	nt plugs at the fo	ollowing mark
indicate muddling jobs, cementing p  It is intended to abandon this well  1. Plug between Dakota - Mo  2. Plug between Dakota - Mo  3. Plug between Mancos - Mo  4. Plug between Mesaverde  5. Plug across Pictured Cl  6. Plug across water sand.  7. Plug in top of hole with  I understand that this plan of work must receive operations may be commenced.  Company EL PASO NATURAL GAS CO	by setting ceme orrison Contact. ancos Contact. esaverde Contact. Lewis Contact. iffs formation. h 4" marker pipe	nt plugs at the fo	ollowing mark
indicate muddling jobs, cementing p  It is intended to abandon this well  1. Plug between Dakota - Mo  2. Plug between Dakota - Mo  3. Plug between Mancos - Mo  4. Plug between Mesaverde  5. Plug across Pictured Cl  6. Plug across water sand.  7. Plug in top of hole with  I understand that this plan of work must receive operations may be commenced.  Company EL PASO NATURAL GAS CO	by setting ceme orrison Contact. ancos Contact. esaverde Contact. Lewis Contact. iffs formation. h 4" marker pipe	nt plugs at the fo	cllowing mark
indicate muddling jobs, cementing post.  It is intended to abandon this well.  1. Plug between Dakota - Markota - Ma	by setting ceme orrison Contact. ancos Contact. esaverde Contact. Lewis Contact. lffs formation. h 4" marker pipe	nt plugs at the fo	cllowing mark

OIL CONSERVATION COMMISSIO
OIL CONSERVATION OFFICE
100. Gopies Received 1
The state of the s
NO. TURNISHED
Garraier
Santa Fo
Proretion Office
Crata Land Office
11 C. C. B.
Transporter 1
File