SIGNED DAN S DAVIS

(This space for Federal or State office use)

## HAUTED STATES

Form approved.

(L'ay 1963)		UNITED STATE		(Other instructions on	Duuget Duleau 110. 42 101451.
, -	DEPART	TMENT OF THE	EINTERIOR	verse side)	5. LEASE DESIGNATION AND SERIAL NO.
		GEOLOGICAL S	URVEY		14-20-0603-9500
CI	11001/ 110	TICEC AND DE	DODTC ON	WELLC	6. IF INDIAN, ALLOTTER OR TRIBE NAME
		TICES AND RE			MATTA TO
(Do not use	this form for prop Use "APPLI	osals to drill or to dec CATION FOR PERMIT-	epen or plug back —" for such propo	to a different reservoir. als.)	NAVAJO
1.					7. UNIT AGREEMENT NAME
OIL [] GAS []					
WELL X WELL OTHER					8. FARM OR LEASE NAME
2. NAME OF OPERATOR  DANI C DATTC					
DAN S DAVIS					DAVIS.
3. ADDRESS OF OPERATOR					5. WELL RO.
4330 EAST TURNEY PHOENIX ARIZONA					
<ol> <li>LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)</li> <li>At surface</li> </ol>					10. FIELD AND POOL, OR WILDCAT
					WILDCAT
		1			11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA
1530° E, W LINE & 2190° N, S LINESEC 11 T22N R14W					
					SEC11T22N R14W
14. PERMIT NO.		15. ELEVATIONS (Sh	ow whether DF, RT,	GR, etc.)	12. COUNTY OR PARISH 13. STATE
					SAN JAUN N MEX
4.0				( h1 D	
16.	Check A	Appropriate Box To	Indicate Natu	re of Notice, Report, o	r Other Data
	NOTICE OF INT	ENTION TO:	1	SUBS	SEQUENT REPORT OF:
TEST WATER SHI		PULL OR ALTER CASIN		WATER SHUT-OFF	REPAIRING WELL
		MULTIPLE COMPLETE	<u> </u>	FRACTURE TREATMENT	ALTERING CASING
FRACTURE TREAT	_			SHOOTING OR ACIDIZING	ABANDONMENT® X
SHOOT OR ACIDIZ	<b></b>	ABANDON*			ADAM DON MAIN 2
REPAIR WELL		CHANGE PLANS		(Other) Report res	ults of multiple completion on Weil
(Other)			!!_	Completion or Reco	ompletion Report and Log form.)
17. DESCRIBE PROPOSE proposed work. nent to this wor	. If well is direc	PERATIONS (Clearly sta- tionally drilled, give su	te all pertinent de ibsurface locations	tails, and give pertinent da and measured and true ver	ites, including estimated date of starting any rtical depths for all markers and sones perti-
110110 00 0001	· <del></del> ,				
WELL NUMB	ER THREE	NEVER CASED	. THE 4	3/4 INCH HOLE	IS PLUGGED WITH
WITH CEME		HE BOTTOM O		— ·	FILLED WITH MUD
··-	X TWENTY				F HOLE. FOUR INCH
PIPE WITH					MPED WITH REQUIRED DATA
MONUMENT		FOUR FT ABO			N SACKS CEMENT USED.
WORK COM		JUNE 66	AT GHOOM		WINDERSON
WORK COM	Preten II	. JUNE CO			២ ស្ត្រីស្លាស់ ស ខ្ទីក្រុង
	•				
	•				
					of and of another of anoth
	•				RECEIVED
			711	TR:	
			COLI	INV /	
			\\$\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\	Arr /	17 1966
			/QLUL	• •	E FEET OF THE STATE OF THE STAT
			111	01960	S S S S S S S S S S S S S S S S S S S
			" " W3	in . COW!	a c. Dedi dedection
			1 20.	ON. Co	on September Man
			/ all	761.3	in the second of
_			10.	201966 SON. COM. DIST. 3	of Surface Control of the Control of
10 I hazahw south- 4	that the taxageton	At this still Assess	<del></del> -		<u> </u>
TO. I HELEDA CELPULATO	THE CHANTOL SOUTH	at true and correct		•	

\*See Instructions on Reverse Side

TITLE \_

TITLE

OWNER

S S S S DATE

Topon it is a series of the se

16JUNE 66