

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-B1424.

5. LEASE DESIGNATION AND SERIAL NO.

14-20-0603-9923

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NAVAJO

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

NAVAJO

9. WELL NO.

#1

10. FIELD AND POOL, OR WILDCAT

AKAH-NEZ *Dev.*

11. SEC., T., R., M., OR BLM. AND  
SURVEY OR AREA

Sec. 23-T23N-R20W

12. COUNTY OR PARISH 13. STATE

SAN JUAN

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

WILLIAM GRUENERWALD & ASSOCIATES, INC.

3. ADDRESS OF OPERATOR

P. O. BOX 909, COLORADO SPRINGS, COLORADO 80901

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

1850' FNL & 780' FEL, Sec. 23-T23N-R20W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☒  
☐  
☐

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐  
☐  
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING


ABANDONMENT\*

☐  
☐  
☒

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Halliburton squeezed perforations with 150 sx at 3,880'. Bedford, Inc. of Farmington, New Mexico shot 5½" casing off at 3,000'. Pulled production casing. Ran 2" tubing to 3050', spotted 45 sx over stub; pulled tubing to 1350' spotted 75 sx with plug from 1250'-- 1350' at base of surface casing. Set P & A marker with 10 sx surface plug.



18. I hereby certify that the foregoing is true and correct

SIGNED

*Clinton C. Kearny*  
CLINTON C. KEARNY

TITLE PETROLEUM GEOLOGIST

DATE AUGUST 18, 1972

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side