10-6-83

F				30-045-25813								
F.loc 1780/N;1980		/W	Elev	6442 GL	Spd	Comp.			.TDCu. ft.	PB		
asing S sg.Perf.	@w_	Cu. ft. Sx. Int	@	w	Sx. Pr Prod. Stim.		v	v	Sx. T		@ 	T Gas
					Grav		1st De	ı. <u>Gas</u>				N S
P	BO/D MCF/D After	Hrs. SICP	PSI	After								
·	TOPS	NITO X		Well Log		TEST DAT	Α			,		
Ojo Alamo		C-103		Plat	X	Schd.	PC	Q	PW	PD	D D	Ref.No.
Kirtland		C-104		Electric Lo	9					<u> </u>	ļ	_
Fruitland		1		C-122					<u> </u>			
Pictured Cliffs		Ditr		Dfa					<u> </u>			 _
Chacra	•	Datr		Dac						<u> </u>		
Cliff House										ļ		
Menefee		1							<u> </u>		<u> </u>	
Point Lookout		-								ļ		
Mancos		1							<u> </u>	 _		
Gallup										<u> </u>		
Greenhorn						ļ		ļ	↓	 		
Dakota							ļ	 		┼	+	+
Entrada						<u> </u>	ļ	ļ			 	
2					Acres 40			<u> </u>	l			

Federal 22-12 #1 F-12-22N-10W

Champlin Petroleum Co.

Caller Service 4104 Farmington, New Mexico 87499

NOV 20 1984

CERTIFIED-RETURN RECEIPT REQUESTED

Champlin Petroleum Company P. O. Box 1257 Englewood, CO 80150

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) well No. 2 Preblo-Porito Federal Unit 22-12, SE/4FU/4 sec. 12, T. 22 h., R. 10 W., San Juan County, New Merico, Lesse MF-34599. As discussed with Bamona J. Rhoden of your company on November 16, 1984, the subject APD is rescinced and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 15 days, it will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, will result in an assessment.

Sincerely yours,

/s/ J. Stan McKee

Assirea Banager

Fnclcsure

cc:

NOV 2 1 1984
OIL CON. DIV.
DIST. 3

