

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

SF-078910

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Lindrith Unit

8. FARM OR LEASE NAME

Lindrith Unit

9. WELL NO.

59

10. FIELD AND POOL, OR WILDCAT

S. Blanco Pic. Cliffs

11. SEC., T., R., M., OR B.L.K. AND

Sec. 32, T-24-N, R-2 -W
N.M.P.M.

12. COUNTY OR PARISH 13. STATE

Rio Arriba NM

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

El Paso Natural Gas Company

3. ADDRESS OF OPERATOR

Post Office Box 4289, Farmington, NM 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface

1650'N, 890'W

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, TO, OR, etc.)

7219'GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.*

- 10-06-88 MOL&RU. Released pkr. TOOH, found bad csg 380' to 64'. Pounded 20/40 sand down csg for plug across perfs. SDFN.
- 10-07-88 TIH to 1024' w/pkr & tbg. PT csg & plug to 1500#, ok. Released pkr. TOOH. Circ hole out bradenhead. Circ 80 sx cmt. SI bradenhead. Squeezed w/40 sx cmt. Held @ 750#. WOC. SDF weekend.
- 10-10-88 TIH w/1 1/4" paddle bit & 1 1/4" workstring. TC @ 36'. Drld out 94' cmt. SDFN.
- 10-11-88 TIH 4 jts. Drld out 90'-95' cmt. Circ. hole. SDFN.
- 10-12-88 Drld, after 15', plugged off. TOOH. Clean tbg. TIH, drld out cmt @ 335'. Circ hole. TOOH. TIH w/csg scraper 2 stds. Reamed csg w/csg scraper. SDFN.
- 10-13-88 TOOH w/csg scraper. TIH, drl out cmt. TOOH. TIH w/scraper. TOOH. PT to 1500#/30 min, ok. Bled off press. TIH w/tbg to clean out sand. Tag sand @ 3178'. Circ haole, started down after about 1', lost circ. Pump 25-30 BW, tried to circ both down tbg & csg, could not. Trip up hole, will not circ. SDFN.
- 10-14-88 Tbg & csg press.up. Blew tbg, unloaded sand & wtr. Pump until circ. Lowered tbg. Ran tbg to TD. Circ w/N2 until clean. Formation taking N2. Pull tbg above perf. Left tbg flowing. SDF weekend.
- 10-17-88 TIH 2 jts tbg. No fill. TOOH. PU pkr, TIH. ND BOP. Set pkr @ 2977'. NU WH. Released rig.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Regulatory Affairs

DATE 01-09-89

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL IF ANY:

TITLE _____

DATE _____

CILCOIL DIV.

*See Instructions on Reverse Side