

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER Dry Hole	5. LEASE DESIGNATION AND SERIAL NO. Jicarilla Apache No. 38
2. NAME OF OPERATOR PAN AMERICAN PETROLEUM CORPORATION	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache Indians
3. ADDRESS OF OPERATOR P. O. Box 480, Farmington, New Mexico	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 790 FAL and 1575 FAL	8. FARM OR LEASE NAME Jicarilla Apache 38 Lease
14. PERMIT NO.	9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6644/RUB	10. FIELD AND POOL, OR WILDCAT Basin Dakota
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA N1/4 NW/4 Section 31 T-24N, R-5W
	12. COUNTY OR PARISH San Arriba
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

As a result of failure to find oil or gas in commercial quantities, we propose to plug and abandon the above well as follows:


- 1) Spot 100 sack plug from TD 6640 to 5340 (Top of Dakota 6436)
- 2) Spot 50 sack plug from 3750 to 3650 (Top of Mesaverde 3692)
- 3) Spot 100 sack plug from 2300 to 2100 (Top of Pictured Cliffs 2212)
- 4) Spot 50 sack plug from 1000 to 900 (Top of Ojo Alamo 955)
- 5) Spot 50 sack plug from 400 to 300 (Base of 8-5/8" casing 347)
- 6) Spot 15 sack plug from 30' to surface
- 7) Erect abandonment marker and clean up location

Verbally approved 7-26-65 John Ward to Frank E. Hollingsworth

RECEIVED

JUL 29 1965

U. S. GEOLOGICAL SURVEY
FEDERAL BUREAU OF RESEARCH



18. I hereby certify that the foregoing is true and correct

ORIGINAL SIGNED BY

Fred L. Saborido, District Engineer

SIGNED

G. W. Estab, Jr.

TITLE

DATE July 28, 1965

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and data well site conditioned for final inspection looking to approval of the abandonment.