Form	9 -331
(May	1963

## UNITED STATES SUBMIT IN TRIPLICATE\* DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

GEOLOGICAL SURVEY

SF078924

	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	

(Do not use this form for pr Use "APP	oposals to drill or to deepen or plug back to a different reservoir. LICATION FOR PERMIT—" for such proposals.)			
OIL GAS WELL OTHE	R	7. UNIT AGREEMENT NA	ME	
2. NAME OF OPERATOR		8. FARM OR LEASE NAME		
Petroleum Consultan	ts, Inc.	Connie	_	
3. ADDRESS OF OPERATOR		9. WELL NO.		
1420 Carlisle Blvd.	, NE Suite 202, Albuqueruqe, NM 87110	5	<u> </u>	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface		10. FIELD AND POOL, OR WILDCAT ESCRITO Gallup		
1850' FNL & 1650' F	EL	11. SEC., T., R., M., OR I SURVEY OR AREA		
		21, T24N, R7N		
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISE	13. STATE	
	7111 KB & 7100 GR	Rio Arrib	New Mexico	
16. Chark	Appropriate Box To Indicate Nature of Notice Report of	r Other Data		

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:		
		WATER SHUT-OFF  FRACTURE TEEATMENT SHOOTING OR ACIDIZING  (Other)  (NOTE: Report results of Completion or Recompletion	REPAIRING WELL  ALTERING CASING  ABANDONMENT*  multiple completion on Well  n Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

5-28-76 thru 6-7-76

Move in - rig up pulling unit - Big A Well Service. retreivable bridge plug and packer to locate casing leak. Found casing leak at 3346'. Squeeze hole in casing with 150 sacks class "B" cement + 0.6% Halad 9 to 650 psi. Wait on cement 24 hours. Drill out. Test casing. Would not hold pressure. Resqueeze hole at 3346' with 150 sacks class "B" + 2% CaCL<sub>2</sub> to 1000 psi. Drill out. Run tubing. Could not swab well dry. Casing repair job unsuccessful. Shut in for further evaluation.

18. I hereby certify that the torgoing is true and content SIGNED TITLE	Agent	рате 9-27-76
(This space for Federal or State office use)		
APPROVED BY TITLE	I	DATE