Furin 3160-5 (November 1983) (Formerly 9-331)	UNITED STATES DEPARTMENT OF THE INTE	SUBMIT IN THIPLICATE. (Other lastructions on re-	Expires August 31, 1985 5. LEASE DESIGNATION AND BESTAL PO. SF-078924
(, , , , , , , , , , , , , , , , , , ,	BUREAU OF LAND MANAGEME	NT	6. IF INDIAN, ALLOTTER OR TRIBE HAME
SUNI (In not we thin t	DRY NOTICES AND REPORTS orm for proposals to drill or to deepen or plu use "APPLICATION FOR PERMIT—" for our	ON WELLS	T. UNIT AGREEMENT HAME
ī.			
OIL XX WELL	OTHE		B. FARM OR LEASE HAME
2. NAME OF OPERATOR			Connie
Grace Petroleum Corporation			9. WELL NO.
3. ADDRESS OF OPERATOR		onso DECEIVED	#21-2
143 Union Blvd	Ste 760, Lakewood, CO	80228 ELEIVED	10. FIELD AND POOL, OR WILDCAT
At surface	port location clearly and in accordance with w.) FWL Section 21	MAY 1 4 1987	Escrito-Lybrook 11. ssc_T, S, M, OR SLK. AND scaver of AREA
	TWD DOCUMENT		Sec. 21, T24N-R7W
NW NW		BUREAU OF LAND MANAGEMEN	! [
	IS. ELEVATIONS (Show whether	FARMINGTON RESOURCE AREA	12. COURTY OR PARIET
14. PERMIT NO.	7281' GL, 7292'		Rio Arriba New Mexico
	7 7201 027 7292	All Parad of	Other Data
16.	Check Appropriate Box To Indicat	e Nature of Notice, Report, or	USHT ESPORT OF:
×	OTICE OF INTENTION TO:	1	
		WATER SEGT-OFF	REPAIRING WELL
TEST WATER SEUT-OF	MULTIPLE COMPLETE	PRACTURE TREATMENT	ALTERING CASING
FRACTURE TREAT	ABANDON*	BEOOTING OR ACIDIZING	ABANDONMENT*
SHOOT OR ACIDIZE		(Other)	- Lutte completion on Well
REPAIR WELL	CHANGE PLANS		s of multiple completion on Well pletion Report and Log form.)
(Other) 17. UESCRIBE PROPUSED OR proposed work. If nent to this work.)	COMPLETED OPERATIONS (Clearly state all pertwell is directionally drilled, give subsurface		
	d that the Connie #21-2 be		
	procedure and wellbore sket		
Please provid	e us with a P&A procedure o	on which formations are	e required to be
perforated an	d cemented.		
			MERELLE

MAY 2 1 1987
OIL CON. DIV.
DIST. 3

	TITLE Operations Engineer	DATE 5/11/87-
(This space for Federal or State office use)	TITLE	1.201987
CONDITIONS OF APPROVAL, IF ANI:	p C-1.	MAREA MANAGER
of 2 ·See	: Instructions on Reverse Side	

LEASE Connic	WELL NO. 21-Z
LOCATION NW NW Sec. 21, TZ4N-R7W	FIELD Escrito - Ly 61004
COUNTY Rio Arriba	STATE New Mexico
COUNTY XIV XIV	TD 6250' KB 7292'
	DF GL _7281'
2 85/8" SURF. CSG.	COMPLETION INTERVALS: Log Tops
a 2/2 'WITH	
/20SACKS.	Picture Cliffs 2546'
SACKO!	
	Point Lookout 4842
	Moncos 5057'
	Gallup 5880'
	Marye Zone 6069'
	WELL HISTORY:
Tox @ 5200'	Perfed Marye (6012-98')
	(4/16/60) Spotted 250 gal
	MCA. Fraced w/ 15,666 sal.
	oil + 15,000 # 20/40. Sanded
1/////// cmd plug from 6034-5989	oil + 15,000 # 20/40. Sanded off. Refrac. w/ 28,770 gal
(IBP @ 6034'	02 + 22,500 # 20/40
	(32 BPM @ 3300 #)
marge (4/16/60) = (6072 - 98') 45PF	
(6072 - 98') 43P	
PBTO @ 6227'	
51/2 " csg. a 6241"	
W/ 150 SXS. 14 #/fx, 15.	5 1/4
	REMARKS:

Procedure to P&A Connie #21-2

- 1. MIRU service rig.
- 2. NU BOP
- 3. PU 32 jts 2-3/8" (161 jts stored in hole). RIH to 5980'.
- 4. Roll hole w/142 bbl 9.2 ppg mud.
- 5. POOH w/tbg.
- 6. Spot & squeeze cement as per BLM's recommendations and requirements (will be available upon approved P&A Sundry).

BUREAU OF LAND MANAGEMENT CALLER SERVICE 4104 FARMINGTON, NEW MEXICO 87499

Attachement of Notice of

Intention to Abandon

Re: Permanent Abandonment Well: 2-2 Connie

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."
- The Farmington Office, telephone (505) 325-4572, is to be notified in sufficient time for a representative to witness all plugging operations. 2.
- Blowout prevention equipment is required.
- The following modifications to your plugging program are to be made (when applicable):

Office Hours: 7:45 A.M. to 4:30 P.M.

GENERAL REQUIREMENTS FOR PERMANENT ABANDONNENT OF WELLS ON FEDERAL LEASES FARMINGTON RESOURCE AREA

- 1. Secure prior approval before changing the approved plugging program.
- 2. Plugging equipment used shall have separate mixing and displacement pumps and a calibrated tank to assure proper displacement of plugs.
- 3. A proper tank or pit will be used to contain all fluids pumped from the well during plugging operations.
- 4. All cement plugs are to be placed through tubing (or drillpipe) and shall be a minimum of 25 sacks or 100 feet in length, whichever is greater.
- 5. Any cement plug placed when well is not full of fluid, or when well may be taking fluid, will be touched after cement has set to verify proper location.
- 6. Mud must be placed between plugs. Minimum consistency of plugging mud must be 9.2 lbs/gal. Brine is to be utilized for mixing mud where possible.
- 7. Within 15 days after plugging work is completed, file Subsequent Report of Abandonment, Form 3160-5, in quintuplicate with Area Manager, BLM, Caller Service 4104, Farmington, New Mexico 87499. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.
- 8. All permanently abandoned wells are to be marked with a regulation marker.
- 9. After plugging work is completed the surface is to be rehabilitated in accord with instructions from the Fluids Surface Management Section of the Farmington Resource Area Office.
- All above are minimum requirements. The period of liability under the bond of record will not be terminated until the lease is inspected and surface work approved.

Please advise this office when the well location is ready for final inspection.

You are further advised that any instructions, orders or decisions issued by the Bureau of Land Management are subject to technical and procedural review pursuant to 43 CFR 3165.3 and appeal pursuant to 43 CFR 3165.4 and 43 CFR 4.700.