

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

## NEW MEXICO OIL CONSERVATION COMMISSION

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-6833-11	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input checked="" type="checkbox"/> WELL GAS <input type="checkbox"/> WELL OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator		Escrito Gallup Unit
3. Address of Operator		8. Farm or Lease Name
135 Grant, Santa Fe, NM 87501		9. Well No.
4. Location of Well		17 (formerly State 1-16)
UNIT LETTER M 660 FEET FROM THE South LINE AND 400 FEET FROM		10. Field and Pool, or Wildcat
THE West LINE, SECTION 16 TOWNSHIP 24 N RANGE 7 W NMPM.		Escrito Gallup
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
7260 GR		Rio Arriba

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We squeezed a hole in the casing on this well in July, 1988. We have been unable to make the well produce properly since. We suspect there is still a hole in the casing. Received verbal permission from Ernie Busch to locate the suspected hole in the casing and repair by squeezing.

RECEIVED

OCT 07 1988

ON 10/06/88

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Elizabeth B. Keeshan TITLE Vice President DATE 10/06/88

APPROVED BY \_\_\_\_\_

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: