

Form 9-331
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

NM-03595

6. IF INDIAN, AGENCY OR TRIBE NAME

7. UNIT AGREEMENT NAME

Escrito Gallup

8. FARM OR LEASE NAME

Escrito Gallup Unit

9. WELL NO.

9 (Formerly Eliz 5)

10. FIELD AND FOML. OR WILDCAT

Escrito Gallup

11. SEC., T., R., M. OR BLM. AND
SURVEY OR AREA

18-24N-7W NMPM

12. COUNTY OR PARISH 13. STATE

Rio Arriba, N.M.

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

BCO, Inc.

3. ADDRESS OF OPERATOR

135 Grant Ave. Santa Fe, New Mexico 87501

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below.
At surface

1850 FSL and 790 FEL Sec 18 T24N R7W NMPM

RECEIVED

JUL 14 1982

U. S. GEOLOGICAL SURVEY

FARMINGTON, N. M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, AT, CR, etc.)

GR 7171

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

XXX

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING



ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and pertinent to this work.)

We intend to set a BP above Gallup perforations (5777 - 5908). We intend to find leak in casing and repair same with cement. Notification of cement job will be made to Minerals Management Service prior to commencement of same. Cement will be allowed to set up a minimum of 72 hours. We will then drill out cement, remove BP, acidize perms if necessary, and place well in operation.

Verbal approval for the above work was obtained from Richard Bell with Minerals Management Service on July 13, 1982. BCO determined we had the casing failure yesterday, July 12, 1982, and due to the lack of drilling mud in the well bore and presence of water within 800 ft. of the surface, we felt it was necessary to repair the well as soon as possible. Work is expected to commence today, July 13, 1982.



18. I hereby certify that the foregoing is true and correct

SIGNED

Harry R. B...

TITLE

President

DATE 7/13/82

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

NMOCG