

1 RR 1 HLB
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM-03595
2. NAME OF OPERATOR BCO, Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 135 Grant, Santa Fe, New Mexico 87501		7. UNIT AGREEMENT NAME Escrito
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1650 FNL 2310 FEL 18-24N-7W NMPM		8. FARM OR LEASE NAME Escrito Unit
14. PERMIT NO.		9. WELL NO. 7
15. ELEVATIONS (Show whether DF, RT, GR, etc.) GL 7280		10. FIELD AND POOL, OR WILDCAT Escrito Gallup
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 18-24N-7W NMPM
		12. COUNTY OR PARISH Rio Arriba
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data (Eliz #4)

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other)

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) Long term shut in

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well was drilled in 1961. Has been operated on a pump jack. Pump is not working. Present pricing for the approximately two and a half barrels of oil a day the well produces makes it uneconomic to repair the pump and place the well back in production. Request permission for long-term shut in.

RECEIVED

OK CON. DIV.
DIST. 9

THIS APPROVAL EXPIRES JAN 08 1991

18. I hereby certify that the foregoing is true and correct

SIGNED Elizabeth B. Keeshan TITLE Vice President

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY:

APPROVED

DATE 10/31/89

DATE JAN 08 1991

Ken Townsend

FOR AREA MANAGER
FARMINGTON RESOURCE AREA

*See Instructions on Reverse Side