

Form 3160-5
(November 1983)
(Formerly 9-331)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

| | | | |
|---|--|--|--|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | | 7. UNIT AGREEMENT NAME Escrito Gallup | |
| 2. NAME OF OPERATOR BCO, Inc. | | 8. FARM OR LEASE NAME Escrito Gallup Unit | |
| 3. ADDRESS OF OPERATOR 135 Grant Avenue Santa Fe, New Mexico 87501 | | 9. WELL NO. 5 (formerly Eliz. 3) | |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1500' FNL 790' FWL Section 18 T24N R7W | | 10. FIELD AND POOL, OR WILDCAT Escrito Gallup | |
| 14. PERMIT NO. | | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 18-24N-7W-N.M.P.M. | |
| 15. ELEVATIONS (Show whether DP, RT, GR, etc.) GR 7099 | | 12. COUNTY OR PARISH Rio Arriba | |
| | | 13. STATE N.M. | |

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐PULL OR ALTER CASING ☐FRACTURE TREAT ☐MULTIPLE COMPLETE ☐SHOOT OR ACIDIZE ☐ABANDON* ☐REPAIR WELL ☐CHANGE PLANS ☐(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐REPAIRING WELL ☐FRACTURE TREATMENT ☐ALTERING CASING ☐SHOOTING OR ACIDIZING ☐ABANDONMENT* ☐(Other) Long-term shut in ☒

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well was drilled in 1961. Has been operated on a pump jack. Pump is not working. Present pricing for the approximately two barrels of oil a day the well produces makes it uneconomical to repair the pump and place the well back in production. Request permission for long-term shut in.

RECEIVED

JAN 10 1990

OIL CON. DIV.
DIST. 3

THIS APPROVAL EXPIRES JAN 08 1991

18. I hereby certify that the foregoing is true and correct

SIGNED Elizabeth B. Keeshan TITLE Vice President

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

APPROVED

DATE 10/31/89

JAN 08 1990
DATE

Ken Townsend

FOR AREA MANAGER
FARMINGTON RESOURCE AREA*See Instructions on Reverse Side
NMOCD