COGO DOKANGO 1 OCC AZTEC HLB . . . Form 3160-5 1 RR Poim approved, (November 1983) UNITED STATES SUBMIT IN TRIPLICATES (Other instructions on re-Budget Bureau Nov 1004-0135 (Formerly 9-331) DEPARTMENT OF THE INTERIOR (Other in Expires August 31, 1985 5. LEASE DESIGNATION AND SECUL NO. BUREAU OF LAND MANAGEMENT NM-03595 SUNDRY NOTICES AND REPORTS ON WELLS 6. IF INDIAN, ALLOTTEE OR TRIBE NAME (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.


Use "APPLICATION FOR PERMIT—" for such proposals.) 7. UNIT AGREEMENT NAME WELL WELL X 4:10 OTHER Escrito Gallup 2. NAME OF OPERATOR 8. PARM OR LEASE NAME BCO, Inc. Escrito Gallup Unit 3. ADDRESS OF OPERATOR 9. WELL NO. 135 Grant Avenue, Santa Fe, NM 87501 6 (Formerly Eliz. 2) LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\* 10. FIELD AND POOL, OR WILDCAT Escrito GAllup 930 FNL and 1650 FWL Sec 18 T24N R7W 11. SEC., T., E., M., OR RLK. AND SURVEY OR AREA NMPM 18-24N-7W NMPM 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, HT, GR, etc.) 12. COUNTY OR PARISH | 13. STATE GR 7139 Rio Arriba NM 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL. FRACTURE TREAT MULTIPLE COMPLETE PRACTURE TREATMENT ALTERING CASING SHOOT OR ACIDIZE ABANDONº SHOOTING OR ACIDIZING ABANDONMENTS REPAIR WELL CHANGE PLANS (Other) (Other)

(Norn: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any nent to this work.) and directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

XX

Drill out bridge plug & test

10/19/90 In May, 1973, a bridge plug was set at 5950 to isolate watered off Gallup perfs. (Mayre member of Gallup) Perforated 5874-5884; 5832-5858; 5776-5790. Fracked and have produced from Skelly member of Gallup. Intend to drill bridge plug at 5950 and test to determine if perforations at 5972-6022 are still making water. If oil is produced will place in production. If water is produced, will set a new bridge plug at about 5950.



18. I hereby certify that the foregoing is true and correct signed Eugebeth B. Keeskan	TITLE	President	DATE10-19-90	
(This space for Federal or State office use)  APPROVED BY  CONDITIONS OF APPROVAL, IF ANY:	TITLE	ACCEPTED FOR RECORD		
SOUND ANT.		MNOCO YS.	2 U 2 1997	

FARMINGTON RESOURCE AREA "See Instructions on Reverse Side

Form 3160-5 (November 1983) Formerly 9-331) DEPART	UNITED STATES MENT OF THE INT AU OF LAND MANAGE		Budget Bureau No. 1004-0135 Expires August 31, 1985  5. Lease designation and serial No. NM-03595
(Do not use this form for prop	TICES AND REPOR	plug back to a different reservoir	6. IF INDIAN, ALLOTTEE OR TELER NAME
OIL GAS []			7. UNIT AGREEMENT HAME
WELL X WELL OTHER  2. NAME OF OPERATOR			Escrito Gallup
BCO, Inc.		,	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR			Escrito Gallup Unit
135 Grant Avenue, San	6 (Formerly Eliz. 2)		
4. LECATION OF WELL (Report location See also space 17 below.)	10. FIELD AND POOL, OR WILDCAT		
At surface	Escrito GAllup		
930 FNL and 1650 FWL Sec 18 T24N R7W NMPM			11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA
	18-24N-7W NMPM		
14. PERMIT NO.	15. ELEVATIONS (Show wheth	her DF RT CR etc.)	12. COUNTY OR PARISH   13. STATE
		R 7139	Rio Arriba NM
16. Ch. J. A			
		ate Nature of Notice, Report, or	Other Data
NOTICE OF INTE	NTION TO:	SURSEC	QUENT REPORT OF:
TEST WATER SHUT-OFF	PELL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT SHOOT OR ACIDIZE	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
REPAIR WELL	CHANGE PLANS	Other) SHUT OFF W	ATER ZONES
(Other)		(NOTE: Report result	s of multiple completion on Well pletion Report and Log form.)
12/30/91	SET BRIDGE PLUG TAS PER THE ATTACH	TO SHUT OFF WATER PRODUCT HED REPORT OF OPERATIONS.	IVE ZONES
		JAN 61992	
		OIL CON. DIV.	그 그를 하는 기업
		DIST. 3	. 23
18. I bereby certify that the foregoing is	true and correct		10 8 7 10 14 14 16 16 16 16 16 16 16 16 16 16 16 16 16
SIGNED	TITLE _	PETROLEUM ENGINEER	DATE 12/30/91
(This space for Federal or State off	ce use)		2
APPROVED BYCONDITIONS OF APPROVAL, IF A	NY:		DATE
	•		Sm-

\*See Instructions on Reverse Side NMOCD

## WORKOVER REPORT

## ESCRITO GALLUP UNIT No. 6 (FORMERLY: ELIZABETH FEDERAL No. 2) 930' FNL x 1650' FWL Sec 18 T24N R7W Rio Arriba County, NM

- 12/10/91 MIRU Bayless Rig #6. Pull rods & tubing.
- 12/11/91 Ran in hole with Halliburton Speed-E-Line drillable bridge and set at 5930'. Tripped out with setting tool. Capped bridge plug with 10' of cement using sand line dump bailer.
- 12/12/91 12/16/91 -Shut down for bad weather.
- 12/17/91 Ran 2-3/8" tubing and tagged bottom at 5925'. Landed 192 joints of 2-3/8" tubing at 5801'. Ran 5-6 swab runs and recovered 11.67 bbl 90% oil. Initial fluid level 3000'. Final fluid level 5500'.
- 12/18/91 12/29/91 Shut in to build fluid and pressure.
- 12/30/91 Swabbed 16.67 bbl 100% oil in 3 runs. Piston came to surface on last run. Last swab run as follows: Csg 475, Piston End @ 380 psi, 1 min tubing 270 psig for difference of 110 psi, 5.42 bbl 100% oil. Rigged down Bayless Rig #6.

Well returned to production.