

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No. <input checked="" type="checkbox"/>

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator J. Granger	8. Farm or Lease Name
3. Address of Operator P. O. Box 507, Farmington, New Mexico	9. Well Name Alpha
4. Location of Well UNIT NUMBER 0 , 000 FEET FROM THE South LINE AND 1650 FEET FROM THE East LINE, SECTION 7 TOWNSHIP 24N RANGE 6E T.M.P.M.	10. Field and Pool, or Wildcat Devil Fork (Gallup)
15. Elevation (Show whether DF, RT, GR, etc.) 6885	12. County Mc Arriba

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was found full of mud on April 17, 1966.
It is proposed to pull tubing, locate leak with packer and retrievable bridge plug, squeeze cement leak, drill out cement, test casing to 3000 psi, perforate upper Gallup, 5694-5706 and 5744-5768, pull bridge plug, clean up well by swabbing, sand oil frac all zones of Gallup with ball sealers, run tubing & rods and return well to production.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____ TITLE **Operator** DATE **6-24-66**

Original Signed by Emery C. Arnold

SUPERVISOR DIST. #3

APPROVED BY _____ TITLE _____ DATE **JUN 27 1966**

CONDITIONS OF APPROVAL, IF ANY: