	West Triumes	£i ;Ut	U Aztec	1 HLB	1. Day	is	
Form 9-231 (May 1963)	UNITED DEPARTMENT OF	STATES F THE INTER CAL SURVEY	SUBMIT IN TRI (Other instruction verse side)	ons on re-	EASE DESIGNATION	911 No. 49_D14	
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)					SF-078959  6. IF INDIAN, CLIOTTEE OR TRIBE NAM.		
OIL GAS WELL WEI  2. NAME OF OPERATO	L Y OTHER				NIT AGREEMENT NA	ME	
BCO, Inc. 3. ADDRESS OF OPERATOR					8. FARM OR LEASE NAME Federal 1-7		
P. O. Box	r 669 Sonto Po N-	w Mexico 8	7501		ELL NO.	<del></del>	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  At surface					10. FIELD AND POOL, OR WILDCAT Basin Dakota		
990 FSL	990 FEL Sec 7	T24N R7W	NMPM		SURVEY OR AREA 24N-7W		
14. PERMIT NO.	. 15. ELEVATIO 7344	NS (Show whether DF,	RT, GR, etc.)	12. c	OUNTY OR PARISH	13. STATE	
16.			(1)	R	io Arriba	N.M.	
	Check Appropriate Bo	l ox to judicate M	ature of Notice, Rep			<u> </u>	
TEST WATER SHU2 FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)	YOFF  X  X  MULTIPLE COMP  ABANDON*  CHANGE PLANS	<del></del>	WATER SHUT-OFF FRACTURE TREATME SHOOTING OR ACIDI (Other)	ZING	REPAIRING WAR ALTERING CAS ABANDONMENT	BING	
Set eas	or COMPLETED OPERATIONS (Clearlif well is directionally drilled, g).	perforate 7	012-7016 with	two shots p	per foot.		
1	mulus with water.				. 0900.		
Frac we	ell with 10,000#'s 1	0 <b>-</b> 20 sand an	d 15,000 gallor	ns water.		• 1	
Place well back into production.						• • • • • • • • • • • • • • • • • • •	
		and the second	Section of the second				
		RI	1973	for W	) (1)		
	•	NON	9 1973 CON. COM.	· :	:		
I hereby continue			DIST. 3				
SIGNED Hang	the foregoing is true and correct		sident	: DA	$_{ extbf{ iny TE}}$ November	06.1973	
(This space for Feder	ral or State office use)			DA	111		
APPROVED BYCONDITIONS OF AP	PROVAL, IF ANY:	TITLE		DA'	re		