

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF-078959

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

BCO, Inc.

3. ADDRESS OF OPERATOR

P. O. Box 669 Santa Fe, New Mexico 87501

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

990' FSL 990' FEL Section 7 T 24N R7W N.M.P.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

7344 KB

12. COUNTY OR PARISH

Rio Arriba

13. STATE

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(Note: Report results of multiple completion on Wells Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

9-1 to 9-6-79 Drilled out cement from 5202 to 6130. Fell through to 6244 and drilled cement from 6244 to 6275. Determined area we fell thru had to be inadequate cement to frac with.

9-7-79 Set packer at 5296 and squeezed perfs 100 sacks Class B, 2% Ca Cl, 8# salt cement

9-10-79 to 9-11-79 Drilled cement from 5804 to 6250.

9-11-79 Ran cement bond log and determined cement over Gallup zone was inadequate to frac. Determined the probability of ever obtaining an adequate cement job to frac thru was nil.

9-12-79 Moved pulling unit off. Operator is trying to determine if other zones in well justify testing. A decision as to future status of well is expected to be made prior to October 1980. Intend to temporarily abandon well until such date.

Attachments:

- 2 copies of cement log run 9-11 to USGS
- 1 copy of cement log run 9-11 to OCC

18. I hereby certify that the foregoing is true and correct

SIGNED Harry R. Bugh

TITLE President

DATE October 11, 1979

(This space for Federal or State office use)

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

