F		9-331 l 1952)	. b
	1	:	; X
		1	

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Indian Agency
Allottee Contract #126
Lease No.

SUNDRY NOT	ICES AN	D REPORTS ON WELLS		
TICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF		
TICE OF INTENTION TO CHANGE PLANS	 	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING		
TICE OF INTENTION TO TEST WATER SHUT-OF	FF	SUBSEQUENT REPORT OF ALTERING CASING		
FICE OF INTENTION TO REDRILL OR REPAIR	WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.		
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REFORT OF ABANDONMENT		
TICE OF INTENTION TO PULL OR ALTER CASI	ING	SUPPLEMENTARY WELL HISTORY		
tice of intention to abandon well	Back x			
(INDICATE ABOVE BY	Y CHECK MARK NAT	TURE OF REPORT, NOTICE, OR OTHER DATA)		
	.	October 3	19.36	
l No." 11-11 is located 1	090 ft. from	$\begin{bmatrix} N \\ S_k \end{bmatrix}$ line and 1000 ft. from $\begin{bmatrix} E \\ W \end{bmatrix}$ line of	of sec.	
4 HS/4 11 241 (% Sec. and Sec. No.) (T	wp.) (R	R.M.P.M. Range) (Meridian)		
		New Mexico		
ldeat-Hogeverde Rio Arriba				
e elevation of the demick hoof al	(County or S rnd pove sea level	,	y)	
ne elevation of the dente noor at	(County or S	is 6823.0 ft.		
te names of and expected depths to objective ing p or fracturing the Point Le pose to coment exposed per perforate the 7 casing	(County or S rad bove sea level DETAILS sands; show sizes, violats, and all other cockout fore reforations and fractur	is 6823.0 ft. S OF WORK weights, and lengths of proposed casings; indicate much rimportant proposed work) settlem and cleaning out, rec ac 5152-5166 w/10 sx, set CI retr	ding jobs, cement-	
te names of and expected depths to objective ing p or fracturing the Point Le pose to consut exposed per perforate the 7 casing i	(County or S rad bove sea level DETAILS sands; show sizes, violats, and all other cockout fore reforations and fractur	is 6823.0 ft. S OF WORK weights, and lengths of proposed casings; indicate mucrimportant proposed work) wation and cleaning out, rec and 5152-5166 w/10 sx, set CI returns the PC formation.	ding jobs, cement-	
te names of and expected depths to objective ing p or fracturing the Point Lapose to conent exposed per perforate the 7 casing in the point in the point in the point in the perforate the 7 casing in the perforate the 7 casing in the perforation in the perfora	(County or S rnd bove sea level DETAILS sands; show sizes, voints, and all other cokout fore rforations and fractur eive approval in writing	is 6823.0 ft. S OF WORK weights, and lengths of proposed casings; indicate mucrimportant proposed work) wation and cleaning out, rec and 5152-5166 w/10 sx, set CI returns the PC formation.	ding jobs, cement-	