


(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Indian Agency \_\_\_\_\_  
Allottee \_\_\_\_\_  
Lease No. \_\_\_\_\_



SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIRS
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

NOV 16 1959

U.S. GEOLOGICAL SURVEY  
FARMINGTON, NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

NOVEMBER 9, 19 59

Well No. **2-2** is located **500** ft. from **N** line and **500** ft. from **E** line of sec. **2**

**2-2** (1/4 Sec. and Sec. No.) **20N** (Twp.) **4W** (Range) **100** (Meridian)  
**UNDEVELOPED - SAGUA** (Field) **250 AMERICA** (County or Subdivision) **NEW MEXICO** (State or Territory)

The elevation of the **drill hole** above sea level is **5741** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Tested Gilling formation after treatment. Unable to recover all lead oil. Abandoned well. Drilled out plug, sand and cement to TD of 7200'. Reset pump to resume pumping Dakota formation.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **JOHNSTON-SEAR**  
Address **2010 Santa Vista St**  
**Albuquerque, N. M.**  
By **W. E. Johnston**  
Title **Partner**

