

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
		5. State Oil & Gas Lease No. E 1207
OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
1. Name of Operator Getty Oil Company		8. Farm or Lease Name Farming "E"
2. Address of Operator P.O. Box 3360, Casper, WY 82602-3360		9. Well No. 2
3. Location of Well UNIT LETTER <u>B</u> <u>764</u> FEET FROM THE <u>North</u> LINE AND <u>1870</u> FEET FROM THE <u>East</u> LINE, SECTION <u>2</u> TOWNSHIP <u>24N</u> RANGE <u>6W</u> NMPM.		10. Field and Pool, or Wildcat Otero Gallup
15. Elevation (Show whether DF, RT, GR, etc.) 6503' DF		12. County Rio Arriba

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL UP ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <u>Acidize</u> <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
---	--	--	---

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

On 10-1-82, MIRU compl. unit. RIH & tag fill @ 5685' (Bottom perf @ 5696') POH.
 On 10-2-82, RU & RIH. Clean out fill to 5835' w/ N₂. POH. RIH w/ pkr to 5475' & set. Acidized Gallup perfs 5600'-5696' w/ 3000 gal of 70 Quality Foam Acid (used a total of 45,507 scf of N₂). Flow well back.
 On 10-4-82, POH w/ pkr. TIH w/ 2 3/8" production tbg & set @ 5665' (SN @ 5645') Rig down & move out. Put on production.



8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____ TITLE Area Superintendent DATE 10-28-82

Original Signed by FRANK T. CHAVEZ SUPERVISOR DISTRICT # 3 DATE 10-28-1982

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: