

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

(Other instructions on reverse side)

EXPIRES AUGUST 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

JICARILLA CONTRACT # 34

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

JICARILLA APACHE TRIBE

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

H.M.

9. WELL NO.

JICARILLA "C" # 22

10. FIELD AND POOL, OR WILDCAT

OTERO GALLUP

11. SEC., T., R., M., OR S.E. AND SURVEY OR AREA

SEC 33 T25N - R5W

12. COUNTY OR PARISH

RIO ARRIBA

13. STATE

NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

95 SEP 14 PM 1:15

2. NAME OF OPERATOR

DOYLE E. BAXTER

OJO ALBUQUERQUE

3. ADDRESS OF OPERATOR

P.O. BOX 27 BLOOMFIELD N.M. 87413

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below.)

At surface

1980' FNL & 660' FEL

"H" SEC 33 T25N - R5W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

6793 Gr.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

I wish to plug the above mentioned well, but have no records to guide me. I am requesting this information from you. I do know this well was 2 staged and later perforated below the Ojo-Alamo & squeezed with cement to the surface. On reentry in 1993, I found lots of cement inside the pipe, but could you let me know where to spot these plugs. With rig availability I would like to get this done as soon as possible. At this time I am still unable to drive, but will go to the location with the crews and supervise the plugging of this well.

RECEIVED
SEP 22 1995
OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED D. E. Baxter

TITLE President

DATE 9/12/95

(This space for Federal or State office use)

APPROVED BY [Signature]

TITLE Chief, Lands and Mineral Resources

DATE SEP 20 1995

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side