

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

6. LEASE DESIGNATION AND SERIAL NO.

SF-079602

7. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED ROOM

89 DEC 28 AM 6:58

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

3. ADDRESS OF OPERATOR
Texaco Inc. (505) 325-4397

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
3300 N. Butler Ave. Farmington, NM 87401

1190' FSL and 1450' FWL Sec 30

14. PERMIT NO.
30039057760001

16. ELEVATIONS (Show whether OF, AT, CR, etc.)
7257' DF

5. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

L.L. McConnell

9. WELL NO.

#1

10. FIELD AND POOL, OR WILDCAT

Bianco - MV
W. Lindrith - Gallup DK

11. SEC., T., R., W., OR BLK. AND SURVEY OR AREA

Sec 30, T25N, R3W

12. COUNTY OR PARISH
Rio Arriba

13. STATE
NM

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☒ Zone Abandonment

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

The subject well is currently being recompleted in the Gallup and Dakota formations. Preliminary results indicate that the well will produce in economic quantities upon completion. The previous producing horizon (Pictured Cliffs) was approaching its economic limit and was successfully squeezed with 150 sx cement at the outset of the current recompletion workover.

Please be notified that Texaco has abandoned the Pictured Cliffs formation and will produce the subject well as a Dakota/Gallup commingled producer.

RECEIVED
DEC 28 1989

CON. DIV

I hereby certify that the foregoing is true and correct

SIGNED Alan A. Klier TITLE Area Manager

DATE 12/27/89

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

BLM(Farm) 4, NMOGCC, AAK

