



BRUCE KING
GOVERNOR

LARRY KEHOE
SECRETARY

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

December 5, 1979

Mr. Harold Aab
Getty Oil Company
P. O. Box 3360
Casper, Wyoming 82602

Re: Getty Oil Company
L. L. McConnell #6
J-30-25N-3W

Dear Mr. Aab:

Rule 108 requires casing failures to be repaired to avoid reservoir damage.

The enclosed production map may be of some assistance in evaluating the well for remedial action.

Please prepare for remedial or abandonment action for the well.

If there are questions, please contact us.

Yours very truly,

A. R. Kendrick
District Supervisor

Enclosures: Rule 108
Production map

xc: Reading file

ARK:no

