

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYIndian Agency Salas

Albuquerque

Allottee and 11.3.7.1.6Lease No. 11.3.7.1.6

RECEIVED

JUL 27 1961

SUNDRY NOTICES AND REPORTS ON WELLS

U. S. GEOLOGICAL SURVEY

FARMINGTON, NEW MEXICO

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

~~Notice of Int. to repair leak in~~

Tubing

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 24, 1962

Well No. 7 is located 1550' ft. from N line and 990' ft. from W line of sec. 2234-35-36-37
(1/4 Sec. and Sec. No.)25N
(Twp.)2W
(Range)R4P1
(Meridian)So. Alamo, P.O. & Store (Chase)
(Field) Deal WellSan Arriba
(County or Subdivision)New Mexico
(State or Territory)The elevation of the derrick floor above sea level is 6676' ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Proposed to:

Rig up pulling unit, pull tubing and repair leak, re-run tubing and put back on production.

Note: On recent Factor Leakage Test well pressures indicated communication between the two sand zones.
Expect to re-appear and put back on production.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Amesbury Petroleum CorporationAddress Box 1469Durango, ColoradoBy R. F. Furse D. F. FurseTitle Foreman