

SKELLY OIL COMPANY

Box 426
Farmington, New Mexico
December 26, 1956

File: Jicarilla "C" No. 10 well

New Mexico Oil Conservation Commission
P.O. Box 697
Aztec, New Mexico

Attention: Mr. Emery Arnold

Dear Sir:

We are requesting permission to dual complete the above captioned well located 1190' from the South line and 1190' from the West line of Section 22-25N-5W, Rio Arriba County, New Mexico.

We plan to drill this well to approximately 3770', or through the Lewis Sands. Set (approximately 3770') of 5-1/2" O.D. 14# J-55 casing, with 200 sacks of regular cement. Perforate and frac the Lewis Sands and Pictured Cliffs formation. After fracing, set Baker Production Packer at approximately 3575'. Run 2" tubing with side-door choke to be set above top of packer. The Lewis Sands to be produced through the 2" tubing, and the Pictured Cliffs formation through the tubing-casing annulus.

Yours very truly,

P. E. Cosper
P. E. Cosper



Box 426
Farmington, New Mexico
December 26, 1956

File: Jicarilla "C" No. 10 well

New Mexico Oil Conservation Commission
P.O. Box 697
Asteo, New Mexico

Attention: Mr. Emery Arnold

Dear Sir:

We are requesting permission to dual complete the above captioned well located 1190' from the South line and 1190' from the West line of Section 22-25N-5W, Rio Arriba County, New Mexico.

We plan to drill this well to approximately 3770', or through the Lewis Sands. Set (approximately 3770') of 5-1/2" O.D. 14# J-55 casing, with 200 sacks of regular cement. Perforate and frac the Lewis Sands and Pictured Cliffs formation. After fracing, set Baker Production Packer at approximately 3575'. Run 2" tubing with side-door choke to be set above top of packer. The Lewis Sands to be produced through the 2" tubing, and the Pictured Cliffs formation through the tubing-casing annulus.

Yours very truly,

(Signed) F. E. Casper
P. E. Casper

