

OIL CONSERVATION COMMISSION  
1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO

June 12, 1962

Continental Oil Co.  
P.O. Box 3302  
Durango, Colorado

Attn: Mr. R. E. Jensen  
District Superintendent

Dear Sir:

I am returning packer leakage test which you have submitted  
for your Jicarilla Apache 22 #1.

I believe that there is an error in the measured 8-day shut-in  
pressure for the Dakota completion as it seems that it should be  
in excess of 200 pounds. I am also unable to understand the  
412-pound discrepancy between the two-pen recorder pressure and  
the deadweight pressure. Does this actually indicate a pressure  
differential or is the recorder in error? In the event that  
there actually this big an error in the two-pen recorder I believe  
that it would be preferable not to enter this pressure on the  
submitted test. If you have any questions on the matter, please  
contact this office.

Yours very truly

Emery C. Arnold  
Supervisor, District #3

ECA:ks

cc: Oil Conservation Commission  
Santa Fe, N.M.

THE CONSERVATION COMMISSION  
1000 RIV BRIDGE RD  
ASTORIA, NEW MEXICO

June 15, 1964

Dear Mr. [Name]:  
Thank you for your letter of June 10, 1964, regarding the [Subject].

I am sorry that I cannot give you a more definite answer at this time, but I will try to get the information you need as soon as possible.

Sincerely,  
[Signature]

The [Subject] is a very important part of our [Program]. We are currently [Action] and will be able to provide you with the information you need by [Date]. I am sorry that I cannot give you a more definite answer at this time, but I will try to get the information you need as soon as possible.

Very truly yours,  
[Signature]

Enclosed for you are [Number] copies of [Document].

Very truly yours,  
[Signature]

Enclosed for you are [Number] copies of [Document].