
Form 9-331 a (Feb. 1951)



(SUBMIT IN TRIPLICATE)

Lease No. NM 04075

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

30	NDRI NOTICE	S AND REPO	JKIS ON	M ELLO	
NOTICE OF INTENTION	TO DRILL	SUBSEQUENT	REPORT OF WATER SHI	UT-OFF	
NOTICE OF INTENTION	TO CHANGE PLANS	SUBSEQUENT	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING		
NOTICE OF INTENTION	TO TEST WATER SHUT-OFF	SUBSEQUENT	SUBSEQUENT REPORT OF ALTERING CASING.		
NOTICE OF INTENTION	TO RE-DRILL OR REPAIR WELL.	SUBSEQUENT	REPORT OF RE-DRILLIN	IG OR REPAIR	
•	TO SHOOT OR ACIDIZE		REPORT OF ABANDONM	IENT	
NOTICE OF INTENTION	TO PULL OR ALTER CASING		RY WELL HISTORY		
NOTICE OF INTENTION	TO ABANDON WELL	Subse	quent Repo	rt of Sand Treatm	
	(INDICATE ABOVE BY CHECI	K MARK NATURE OF REPORT	NOTICE, OR OTHER DA	TA)	
			October	14th	, 1958
Well No. 4	is located 790 ft.	from ${N \brace S}$ line and	1850 ft. from	$\left\{ \begin{matrix} E \\ W \end{matrix} \right\}_{\text{line of se}}$	c. 23
NW/4 NE/4 (% Sec. and Sec.	Sec. 23 25N	(Range)	M. P. M. (Meridian)		
S. Blanco	PC Ext.	Rio Arriba			<u> </u>
(Field)	(0	County or Subdivision)	(St	tate or Territory	
The elevation of t	the derrick floor above s	sea level is7234	t.		(ED)
	D	ETAILS OF WOR	K	1 1000	958
State names of and exp	ected depths to objective sands; s ing points, a	how sizes, weights, and leng nd all other important prop	ths of proposed casing losed work)	indicate mudding	jobs, cement
9 -16- 58	TD 3735' RKB. 3662-80' with 4 25,000 gallons 4,000 gallons w treating pressu balls during tr barrels per min	shots per for water and 30, water. Breakdure 1600-1800/ reatment. Ave	ot. Sandf 000# sand, lown pressu . Dropped	raced with flushed ore 3000#, 30 rubber	i with
9-18-58	After 39 hours	flowing in ex	cess of 5,	000 MCF/da	By.
Company BEN	is plan of work must receive appl SON-MONTIN-GREEF West Broadway			perations may be con	mmenced.
	and management that the same	rton -	Ву 		
Far	mington, New Mex		-		
		Ti	tle Vie	e-Preside	nt