(SUBMIT IN TRIPLICATE)

DEPA

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Allottee 1	caril	la T	el ba
Lease No	Lease	No.	64

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTIO	ON TO DRILL	s	SUBSEQUENT REPORT O	F WATER SHUT-OFF	<u>_</u>
OTICE OF INTENTIO	N TO CHANGE PLANS	s	SUBSEQUENT REPORT O	F SHOOTING OR ACIDIZING	
OTICE OF INTENTIO	N TO TEST WATER SHUT-OF	T	SUBSEQUENT REPORT O	F ALTERING CASING	
OTICE OF INTENTIO	N TO REDRILL OR REPAIR	WELL S	SUBSEQUENT REPORT O	F REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE			SUBSEQUENT REPORT O	F ABANDONMENT	
IOTICE OF INTENTIO	N TO PULL OR ALTER CASH	NG S	SUPPLEMENTARY WELL	HISTORY	
OTICE OF INTENTIO	ON TO ABANDON WELL				W1S-1358
		<u> </u>			
	(INDICATE ABOVE BY	CHECK MARK NATUR	E OF REPORT, NOTICE,	OR OTHER DATA)	
				June 17th	
4 m/ 4 s	Sec. 19	25N 41	7	ft. from W line of	sec. 19
(14 Sec. and Se		wp.) (Ran	I :		_
Blanco (Field)		(County or Subo	20.20.	(State or Territory)	-5
	the derrick floor ab	DETAILS (OF WORK	oposed casings; indicate mudd rk)	ing jobs, cement-
	TD 3291' REI J-55 casing Temperature Pressured up	DETAILS (sands; show sizes, weight, and all other in S. Set S1 at 3290' to survey show	OF WORK Ights, and lengths of proposed work Joints 330 with 150 second top of	8: of 5-1/2" (cks coment.	D 15.5# C;
2- 9-58	TO 3291' REI J-55 casing Temperature	DETAILS (sands; show sizes, weight, and all other in S. Set S1 at 3290' to survey show	OF WORK Ights, and lengths of proposed work Joints 330 with 150 second top of	8: of 5-1/2" (cks coment. cks coment et 1)	D 15.5# C; decrease
ate names of and ex 2- 9-58 4-28-58	TD 3291' REI J-55 casing Temperature Pressured up	DETAILS (sands; show sizes, weight oints, and all other in Set 81 at 3290' to survey show on casing	of Work ights, and lengths of proposed work coints 330 with 150 sa count top of to 1000%.	8 of 5-1/2" Con.	D 15.5# C; decrease
ate names of and ex 2-9-58 4-28-58 I understand that the second secon	TD 3291' REI J-55 casing Temperature Pressured up in one hour.	DETAILS (sands; show sizes, weight oints, and all other in 8. Set 81 et 3290' to survey six on casing	of Work Ights, and lengths of proposed work Joints 330 With 150 sa With 150 sa With 160 sa	8 of 5-1/2" Con.	D 15.5# C; decrease
2- 9-58 4-28-58 I understand that to sompany	TD 3291 REI J-55 casing Temperature Pressured up in one hour.	DETAILS (sands; show sizes, weight oints, and all other in 8. Set 81 et 3290' to survey six on casing	of Work Ights, and lengths of proposed work Joints 330 With 150 sa With 150 sa With 160 sa	8 of 5-1/2" Con.	D 15.5# C; decrease
2- 9-58 4-28-58 I understand that tompany	TD 3291' RKI J-55 casing Temperature Pressured up in one hour.	DETAILS (sands; show sizes, weight oints, and all other in 8. Set 81 et 3290' to survey six on casing	of Work Ights, and lengths of proposed work Joints 330 With 150 sa With 150 sa With 160 sa	8 of 5-1/2" Con.	D 15.5# C; decrease