

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT" for such proposals.

**RECEIVED**  
MAY 28 1999

99 MAY 24 AM 10:24  
ALBUQUERQUE, N.M.

5. Lease Designation and Serial No.

JICARILLA 148

6. If Indian, Allottee or Tribe Name

JICARILLA APACHE

7. If Unit or CA, Agreement Designation

8. Well Name and No.

JICARILLA CONTRACT 148 13

9. API Well No.

30-039-06042

10. Field and Pool, or Exploratory Area

LINDRETH GALLUP DAKOTA WEST

11. County or Parish, State

RIO ARRIBA NEW MEXICO

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

AMOCO PRODUCTION COMPANY

Attention:

MARY CORLEY

3. Address and Telephone No.

P.O. BOX3092 HOUSTON, TX 77253

281-366-4491

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1005' FNL

1750' FWL

Sec. 15 T 25N R 5W

UNIT C

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☒ Other BLM LETTER DATED 3/19/99
- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give

subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Amoco Production Company request permission to maintain the subject well in a shut in status pending surface equipment repair. The Dakota formation has been plugged off and the wellbore is open to the Gallup only. We are in the process of having the separator repaired and will attempt to flow the well upon completion of separator repair work. If the well will not sustain flow, we will shut in, allow to build up pressure and flow at least a couple of days per month. Ultimately, we will evaluate to pull rods and install plunger lift equipment.

14. I hereby certify that the foregoing is true and correct

Signed

Title

Sr. Business Analyst

Date

05-19-1999

(This space for Federal or State office use)

Approved by

Title

Lands and Mineral Resources

Date

MAY 27 1999

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious, or fraudulent statements or representations as to any matter within its jurisdiction.