

	1	2	
			0

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4
Approval expires 12-31-60.

Land Office Jicarilla Tribal
Lease No. Contract No. 145
Unit SE/4, Sec. 12, T-25N,
R-5W, N.M.P.M., Rio Arriba
County, New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 2, 1958

Well No. Jicarilla
7-4 is located 790 ft. from S line and 1630 ft. from E line of sec. 12
SW/4, SE/4, Section 12 25N 5W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
South Blanco-Pict. Ctr. Rio Arriba New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 7391 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

- 1- Ran 95 joints $5\frac{1}{2}$ " J-55, 15.50# casing. Landed at 3873 R.K.B. Cemented w/150 sacks regular cement w/2% gel on May 26, 1958.
- 2- Perf. 4 shots 1 foot 3704 to 3764. Sand-Water frac. w/100,000# sand and 80,000 gallons of water on May 30, 1958.
- 3- Ran 117 joints $2\frac{3}{8}$ " 4.60# J-55 tubing. Landed at 3744 R.K.B. on May 31, 1958.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Southern Union Gas Company

Address 1001 Burt Building
Dallas, Texas

By Sam J. Lillate

Title Drilling Superintendent 9 18 507