

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN DUPLICATE
(Check "FUTURE USE" on re-
verse side)Form approved,
Budget Project No. 45-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 078884

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
See "APPLICATION FOR PERMIT" for such proposals.)

7. UNIT AGREEMENT NAME

Canyon Largo Unit

8. FARM OR LEASE NAME

Canyon Largo Unit

9. WELL NO.

93 (PSA)

10. FIELD AND FOOT, OR WITH/OUT

So. Blanco P.C.

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREASec. 12, T-25-N, R-6-W
NMPM

12. COUNTY OR PARISH

Rio Arriba

13. STATE

NM

1. OIL
WELL ☐ GAS
WELL ☒ OTHER:

2. NAME OF OPERATOR

El Paso Natural Gas Company

3. ADDRESS OF OPERATOR

PO Box 990, Farmington, NM 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

990'N, 990'E

14. PERMIT NO.

15. ELEVATIONS (Show whether DE, ET, GR, etc.)

6702'GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION OF:

TEST WATER SHUT-OFF

☐

PULL OR ALTER CASING

☐

FRACTURE TREAT

☐

MULTIPLE COMPLETE

☐

SHOOT OR ACIDIZE

☐

ABANDON*

☒

REPAIR WELL

☐

CHANGE PLANS

☐

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐

REPAIRING WELL

☐

FRACTURE TREATMENT

☐

ALTERING CASING

☐

SHOOTING OR ACIDIZING

☐

ABANDONMENT*

☐

(Other)

(NOTE: Report results of multiple completion or Well
Completion for Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

Due to non-production it is planned to plug and abandon this well in the
following manner:

Spot a 20 sack cement plug to cover perf (2820-28-4').

Shoot off 2 7/8" casing at free point and spot a 20 sack cement plug on casing stub.

If cut off is made below the base of the Ojo Alamo, spot a 35 sack cement plug
over the Ojo Alamo.

Spot a 15 sack cement plug at base of surface casing.

Spot a 10 sack cement plug at the surface with a Plug & Abandon marker, clean
up location.

18. I hereby certify that the foregoing is true and correct

SIGNED

Original Signed P. A. W.

TITLE

Petroleum Engineer

DATE

October 4, 1971

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
DIAPHRAGM 2010