Form 3160-5 (December 1989)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: September 30, 1990

5. Lease Designation and Serial No.

			SF Federal #080565	
Do not	SUNDRY NOTICES AND REP use this form for proposals to drill or to dec Use "APPLICATION FOR PERMIT-	6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE			7. If Unit or CA, Agreement Designation	
1. Type of W	/cll			
Oil			8. Well Name and No.	
2. Name of Operator .			Florance #4	
Graham Royalty, Ltd.  3. Address and Telephone No.			9. API Well No.	
1675 Larimer St., Suite 400, Denver, CO 80202 (303) 629-1736			10. Field and Pool, or Exploratory Area	
4. Location of Well (Frotage, Sec., T., R., M., or Survey Description)			Tapacito Pictured Cliffs	
987' FEL, 1680' FSL 7-5-25N-3W			11. County or Parish, State	
			Rio Arriba, New Mexico	
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				
	TYPE OF SUBMISSION TYPE OF ACTION			
	Notice of lutent	X Abandonment	Change of Plans	
	DECEIVE	Recompletion	New Construction	
	Subsequent Rank	Plugging Back	Non-Routine Fracturing	
	X Final Abandonment NaMAR1 0 1993	Casing Repair Altering Casing	Water Shut-Off Conversion to Injection	
		Other	Conversion to injection	
	OIL CON. DIV	(Note: Report result Recompletion Repor	s of multiple completion on Well Completion or t and Log form.)	
13. Describe Pr	roposed or Completed Operations (Creary) state all pertinent details,	and give pertinent dates, including estimated date of stan	ting any proposed work. If well is directionally drilled.	
12/11/92	ubsurface locations and measured and true vertical depths for all markover unit. ND wellhead. NU B		').	
12/12/92	TIH w/4½" csg scraper on 118 jts. tubing. TOOH w/tubing. RU Schlumberger. Shot 4 sqz holes at 1630' KB & 4 sqz holes @ 235' KB. RD Schlumberger. TIH w/4½" retainer on tbg. Set at 3702' KB.			
12/13/92	SDFS.			
12/14/92	not break down. Stung out of retainer. Spotted a Class B neat cement plug from 3702' to 3330' (28 sx). PUH to 3330'. Circulated hole w/9#, 50 vis mud. TOOH w/tbg. RIH 442" Sretainer to 1602'. Circ hole w/mud. Set retainer at 1602'. Sqzd perfs @ 1630' w/25 sx Class B cmt. Stung out of retainer and spotted 200' cmt plug on top (15.5 sx). PUH to 252'. Circ hole w/mud. Closed BOP. Pressured up on tbg & est. circ out bradenhead. Circ cement to surface and TOOH filling csg w/cement (81 sxs). Circulated out + 10 sxs an ground.			
12/22/92	Cut off csg 4' below GL. Welded on pla restored in spring.	te and installed P&A marker. Locat		
14. I hereby cer	rufy that the forespinglis true and correct			
Signed	Luy Howard Title	Sr. Petroleum Engineer	Date	
Approved by Muley Mondy Title acking area Manage Date 3/8/93				
Conditions of approval, if any: // NMOCD				

Denver District

93 JAN 14 AM 11: 28

070 FARMINGTON, NM

January 8, 1993

U.S. DEPARTMENT OF THE INTERIOR Bureau of Land Management 1235 LaPlata Highway Farmington, New Mexico 87401

Re: P & A Sundry Notice

Florance #4
Tapacito Field

Rio Arriba Co., New Mexico

## Gentlemen:

Enclosed is a Sundry Notice which details the permanent abandonment of the Florance #4. Graham Royalty, Ltd. operates the subject well.

If you have any questions regarding the above, please call me at 303-629-1736.

Sincerely,

GRL PRODUCTION SERVICES COMPANY Agent-In-Fact for Graham Royalty, Ltd.

Terry S. Holzwarth Sr. Petroleum Engineer

TSH/tah

Attachment