| Form 9-331 (May 1963) | UNITED STATES SUBMIT IN TRIPLICATE DEPARTMENT OF THE INTERIOR (Other Instructions on Interior | G. LEASE DESIGNATION AND SERIAL NO. |
|--|---|---|
| (Do not use | SUNDRY NOTICES AND REPORTS ON WELLS this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.) | SF-080565A 6. IF INDIAN, ALLOTTEE OR TRIBE NAME |
| OIL G: | ELL Y OTHER | T. UNIT AGREEMENT NAME |
| Gulf 3. ADDRESS OF OPE | 0il Corporation | 8. FARM OR LEASE NAME Stevie Joe |
| P. O. 4. LOCATION OF WE See also space 1 At surface | Box 670, Hobbs, NM 88240 | 9. WELL NO. 1 10. FIELD AND FOOL, OR WILDCAT Tapacito Picture Cliff; 11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA |
| 14. PERMIT NO. | 15. ELEVATIONS (Show whether DF, RT, CR, etc.) | Sec 5-T25N-R3W 12. COUNTY OR PARISH 13. STATE Rio Arriba NM |
| Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data Notice of Intention to: Subsequent Report of: Subsequent Report of: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) To describe Proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) POH with tubing. Set CIBP at 3710'. Spot cement plug 3710'-3440' with Class "B" neat. Perf 170' with (2) ½" JH 180°. Attempt to circ down 4½" casing & up 7-5/8" casing. Set cement retainer at 120', test 3000#. Pump 40 sacks Class "B" neat cement; squeeze 500#. Spot cement plug 120' to surface with Class "B" neat. Place dry hole marker. Clean and clear location. | | |
| | RECEIVED APR 166 U.S. SECURIAL SULVEY FARMING OR, N. IV. | AFR SATE INCINETA |

ルス

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

NMOCC