Form 9-331 (May 1963)

14. PERMIT NO.

UNITED STATES SUBMIT IN TRIPLICATES DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

SE	080565A
~ 4 .	

Sec 6-T25N-R3W 12. COUNTY OR PARISH | 13. STATE

GEOLOGICAL SURVEY	
SUNDRY NOTICES AND REPORTS ON (Do not use this form for proposals to drill or to deepen or plug back to use "APPLICATION FOR PERMIT—" for such proposals.	to a different reservoir.
1. OIL GAS OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Gulf Oil Corporation	8. FARM OR LEASE NAME Stevie Joe
3. ADDRESS OF OPERATOR P. O. Box 670, Hobbs, NM 88240	9. WELL NO
4. I MATION OF WELL Report location clearly and in accordance with any State See also space 17 below.) At surface 790 FNL & 1850 FWL	Tapacito PC 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
//C 1111 G 1000 1WH	

***************************************		Percent.			Rio
16.	Charle Appropriate	Roy To Indicate I	Vatura of Natica	Rapart or Ot	har Data

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:					
	r1		[]	· I			
TEST WATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OFF		REPAIRING WELL	
FRACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT		ALTERING CASING	
SHOOT OR ACIDIZE		ABANDON*		SHOOTING OR ACIDIZING		ABANDON MENT*	
REPAIR WELL		CHANGE PLANS		(Other)			
(Other) Run Packe	r		_X	(Note: Report res Completion or Reco	ults of impletl	multiple completion on Well on Report and Log form.)	1

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Run production packer to increase productivity.



SIGNED SIGNED		Area Engineer	APPRQVED
(This space for Federal or State office use)			MAR 4 1981
APPROVED BY	TITLE _	NMOCC	JAMES F. SIMS
17 1		MAIOOA	DISTRICT OIL & GAS SUPERVISOR