OIL CONSERVATION COMMISSION 1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO

September 6, 1967

Mr. W. K. Dietrich Continental Oil Company P. O. Box 1621 Durango, Colorado 81302

> Re: Packer-leakage test Continental Oil Co. Jicarilla 28 #3 P-35-25N-4W

Dear Mr. Dietrich:

The packer-leakage test report received in this office September 1, 1967, is returned herewith.

Please cause the well to be retested.

During Flow Test No. 1 the shut in pressure decline may or may not have resulted from fuel gas use. Conduct the retest in such manner as to prove zone separation.

Yours very truly,

A. R. Kendrick Engineer, District #3

ARK:mc

Encl.

रिंप ,०३० व्यक्ति

dultist (1. 1. 1. dust tantino, (1. dustrial) 1. 2. dustrial fuctorial (1. dustrial)

Cos Beeks Jessés (98 1986 timeste (1800) 1986 timeste 1986 25

Less de. Mistrica:

දේ මා මෙම අතුර විශාවිත වේ සිට වෙන්න වෙන්න වෙන්නේ දෙන මෙන්නේ මෙන්නේ මෙන්නේ මෙන්නේ මෙන්නේ මෙන්නේ මෙන්නේ මෙන්නේ ම මෙන්නේ මෙන්න

· Programme and the state of a state of the state of the

the important T_i of the whole is pressure that into day of they the constraint T_i of the interval case in the constraint T_i of the constrain

MUST NOTE THETY.

で、このではないできます。
 これないのはできます。
 これないのはできます。

11:196

ា ខា