

submitted in lieu of Form 3160-5

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well  
GAS

2. Name of Operator  
MERIDIAN OIL

3. Address & Phone No. of Operator  
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M  
790'FNL, 870'FEL, Sec.9, T-25-N, R-6-W, NMPM

5. Lease Number  
SF-079177  
6. If Indian, All. or  
Tribe Name  
7. Unit Agreement Name  
Canyon Largo Unit  
8. Well Name & Number  
Canyon Largo U #140  
9. API Well No.  
30-039-20075  
10. Field and Pool  
Otero Chacra  
11. County and State  
Rio Arriba Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission	Type of Action
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other -
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Conversion to Injection

13. Describe Proposed or Completed Operations

1-24-95 MIRU. ND WH. NU BOP. Ran stress test on csg. TIH to 2576' w/1 1/4" tbg. SDON.  
2-1-95 TIH w/gauge ring to 2572'. TOO. TIH w/2 7/8" cmt retainer, set @ 2570'. Plug #1: pump 35 sx Class "B" cmt below retainer through 1 1/4" tbg. Not able to sting out of tbg. SDON.  
2-2-95 Cut 1 1/4" tbg @ 2070'. Tbg still stuck. Cut tbg @ 1900'. POOH w/tbg. Perf 2 sqz holes @ 1875'. Tried to set cmt retainer @ 1875'. Retainer failed to set. (Received verbal approval to change plans from Herman Lujan, BLM). TOO. w/cmt retainer. Injected 20 sx Class "B" cmt down csg & into perms. Displaced to 1750' w/wtr. SDON.  
2-3-95 Tagged cmt @ 1770'. TOO. Perf 2 sqz holes @ 330'. Establish circ w/10 bbl wtr. Pump 100 sx Class "B" cmt down csg and out bradenhead. Circ 1 bbl cmt out bradenhead. ND BOP. Cut off WH. Top off csg strings w/5 sx cmt. Install dry hole marker w/10 sx cmt. RD. Well plugged and abandoned 2-3-95.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Affairs Date 2/14/95

(This space for Federal or State Office use)

APPROVED BY \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_

CONDITION OF APPROVAL, if any:

APPROVED

FEB 17 1995

DISTRICT MANAGER