
Form	9-331
(May	1963)

	n 9-331	INITED STATES	SUBMIT IN TRIPLICATE*  (Other instructions on re-	Form approved. Budget Bureau No. 42-R1424.
(Ma	DEPARTM	IENT OF THE INTERIO	R verse side)	5. LEASE DESIGNATION AND SERIAL NO.
		EOLOGICAL SURVEY		147 gg 1
				6. IF INDIAN, ALLOTTEE OR THIBE NAME
	SUNDRY NOTI	4 WELLS	Single Si	
	(Do not use this form for proposa	als to drill or to deepen or plug bac TION FOR PERMIT—" for such prop	k to a different reservoir.	Jicarilla Apachei
	030 1111 1111	0		7. UNIT AGREEMENT NAME
OIL GAS X OTHER				THE STATE OF THE S
2.	WELL WELL A OTHER NAME OF OPERATOR			8. FARM OR LEASE NAME
۵.		nontal Oil Company		AXE Apache July 3
Continental Oil Company 3. ADDRESS OF OPERATOR				9. WELL NO. 12 TO THE PARTY OF
•	200 North Wolcott, Casper, Wyo. 82601			The state of the s
4.	LOCATION OF WELL (Report location cl	early and in accordance with any St		10 RIELD AND POOL, OR WILDCAT -
	See also space 17 below.) At surface			Otero-Chacra
	1450'	FSL, 1190' FWL		11 SEC., T., R., M., OR BLK, AND
				A SOUTH SOUTH
				Sec. 8,4 T25N,4 R5W
14.	PERMIT NO.	15. ELEVATIONS (Show whether DF, R	RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
		6684' Gr., 6695'	RB	Rio Arriba New Mexico
	CL 1 A	Pau Ta Indiagta Na	ture of Notice Report or	Other Data = B A S A S
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or C			
	MOTICE OF INTENTION TO:		QUENT REPORT OF A CONTROL OF A	
	TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
	FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
	SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
	REPAIR WELL	CHANGE PLANS	(Other)	s of multiple completion on Well
	(Other)		Completion or Recom	pletion Report and Log form.)
17	. DESCRIBE PROPOSED OR COMPLETED OPE proposed work. If well is directionent to this work.)*	RATIONS (Clearly state all pertinent onally drilled, give subsurface location	details, and give pertinent date ons and measured and true verti	s, including estimated date of starting any cal depths for all markers and zones perti-
				200 H 120 H
	Commenced drilling 9:0	set at 208 with 120 min		
sacks Class "A" cement with 3% CaCl2. Plug down 9:45 A.M., 2-7-69. WOC. Tested with 800 psi for 10 minutes. Okay. Drilled to TD 3870'. Ran Schlumberger IES with 800 psi for 10 minutes.				
	with 800 psi for 10 mi	n Schlumberger Ind 10g		
		1 ·	ADE INTO PASIDO SE	at at 10 John wrent 19
	sacks Liteweight with	.5 of 1% D-30 (frict:	ion reducer), lollo	wed by you sacks you you
	Pozmix "A" with 2% ge	$1, 6 \frac{1}{4}$ /sack Gilson:	ite and .5 of $1\%$ D	30. Plug down 11:45 P.M.,
	2-12-69 with 1500 psi	and 200 gallons acet:	ic acid and 55 barr	els KCI. Kig released
	11:59 P.M., 2-12-69.	WOC.		anne (1) John Sand Sand Sand Sand Sand Sand Sand Sand
				and the second s
				175. 100 miles
		FOFE	, · · · ·	Transcription of the control of the
		OHTHA		thr edge edge of e thr union u
	/	UTPLIAFY	my to the	et biracquag hathilitier recent for require the problem was formed a problem and represent formed are red to a recent a problem and a problem
	/		المستريب المستريب	A State of the Sta
	Pozmix "A" with 2% ge? 2-12-69 with 1500 psi 11:59 P.M., 2-12-69.	FEB 1 8 1000	•	Legot sinsegory withindre to come for bon was insegory withindre to come for some for the discisling and the come for the



Composite procedures and I office and I offi

18. I hereby certify that the foregoing is true and correct TITLE Administrative Section Chief -- 1 My Joeal, area, are stated at the large state at the l (This space for Federal or State office use) APPROVED BY \_\_\_\_\_\_CONDITIONS OF APPROVAL, IF ANY:

