

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

Jicarilla 70

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Jicarilla 70

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Lindrieth Gallup - Dak. S.

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 33 T24N-R4W

12. COUNTY OR PARISH 13. STATE

Rio Arriba

NM

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Chace Oil Company, Inc.

3. ADDRESS OF OPERATOR

313 Washington, S.E., Albuquerque, N. M. 87108

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below.)  
At surface

1590' FWL - 1080' FHL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6428 GR

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:


TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☒SHOOTING OR ACIDIZING ☒(Other) Progress ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☐(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Ran sch. T.D.T. Log from 4500' 2600'. Pulled 6081.74' of 2 3/8" tbg. Ran correlation and bond logs. Perforated from 2708 - 18' - 2 shots per foot (3 1/8" Bullets) Set Guiberson Retrivable Bridge Plug at 2834. Pulled tbg up to 2717. Broke down perfo. Break down pressure 1600 # ISIP 200# swabbed water and gas. Pulled tubing Fraced well with 250 gal 7% HCL, 357 bbls slick water and 15000# of 20-40 Sand. ISIP 250#, SI after 15" 100# - after 40" 210#. SI 2 hrs. opened well flowed 1 hr. swaubed well in - flowed well off and on <sup>For</sup> three days to clean up. SI for pressure build up 4-21-76.



18. I hereby certify that the foregoing is true and correct

SIGNED

Cary President

DATE 4/26/76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY  
WATER RESOURCES DIVISION  
WASHINGTON, D. C. 20506  
OFFICE OF THE CHIEF OF BUREAU  
WASHINGTON, D. C. 20506  
U. S. GEOLOGICAL SURVEY  
WASHINGTON, D. C. 20506